


#### **EWR D&I ANNOTATION**



Artemis #: 000001L064001DP88

Record Created Date: 07/24/2007

Printed Date: 08/01/2007

THE DRIVER OF THE SUBJECT VEHICLE WAS TRAVELING NORTHBOUND ON A LOCAL ROAD WHEN, FOR UNKNOWN REASONS, THE VEHICLE VEERED OFF THE ROAD INTO A DITCH, WHERE THE VEHICLE STRUCK A TREE. THE DRIVER SUFFERED SEVERE INJURIES, HOWEVER, TWO PASSENGERS SUFFERED FATAL INJURIES. NO DEFECT ALLEGATIONS WERE INCLUDED IN THE RESPONSE. THE POLICE REPORT INDICATES THAT THE DRIVER FAILED TO CONTROL THE

Description:

VEHICLE. THE REPORT ALSO INDICATES THAT ALL THREE VEHICLE OCCUPANTS FAILED TO WEAR THWIE SAFETY RESTRAINTS. THE OWNER OF THE VEHICLE TOLD POLICE THAT THE VEHICLE HAD PREVIOUSLY RECEIVED RECALL RELATED WORK ON THE AIRBAGS AND WINDSHIELD WIPER SWITCH. THE SUBJECT VEHICLE MANUFACTURER HAS MADE NO ASSESSMENT OF THIS CRASH EVENT. THERE ARE NO APPARENT SAFETY RECALLS THAT

RELATE TO THE ISSUES IN REGARDS TO THIS CRASH EVENT.

Print Close

Copyright @ 2007 Artemis. All rights reserved.

ScI · CAOS-049



1200 New Jersey Ave., S.E. Washington, D.C. 20590

## CERTIFIED MAIL RETURN RECEIPT REQUESTED

MAY - 7 2007

Ms. Gay Kent General Motors Corp. Mail Code 480-210-G11 30001 Van Dyke Warren, MI 48090 NVS-217ph DI07-044

Dear Ms. Kent:

The Office of Defects Investigation (ODI) of the National Highway Traffic Safety Administration (NHTSA) has received information about certain death and injury incidents reported by General Motors (GM) in its light early warning report from 4th quarter of 2006. We are writing to request additional information about the following incidents:

#### **Selected Death and Injury Incidents**

For Reporting Category: L

For the following Sequence IDs: 30, 40, 88, 91, 103, 116, 135, 137, 140, 155, 221, 244, 246, 256, 257, 273, 274, 285, 295, 345, 360, 368, 401, 424, 436, 439

Unless otherwise stated in the text, the following definitions apply to these information requests:

**Incident:** each incident identified in the table above.

<u>Claim and Notice</u>: shall have the meanings stated in 49 CFR §579.4(c). Claim and notice also specifically refer to the claim(s) and notice(s) that are the predicate for the early warning report on the incident.

Manufacturer: refers to GM.

<u>Vehicle</u>: the vehicle produced by GM that is identified in the claim or notice.

Tire: the tire produced by GM that is identified in the claim or notice.





**Equipment:** the item of motor vehicle equipment produced by GM that is identified in the claim or notice.

<u>Defect</u>: means any failure, malfunction, lack of durability, or other problem in performance, construction, a component, or material of a motor vehicle or piece of motor vehicle equipment.

<u>Document</u>: "Document(s)" is used in the broadest sense of the word and shall mean all written, typed, graphic and photographic matter whatsoever (except autopsy photographs), be it in original, copy or electronic form. Any photograph originally produced in color must be provided in color and in electronic form, if possible. Furnish all documents whether verified by GM or not. If a document is not in the English language, provide both the original document and an English translation of the document. Document(s) includes all documents in GM custody and/or control.

Please provide numbered responses to the following inquiries, repeating the applicable request verbatim before each response. After GM's response to each request, identify the source of the information and indicate the last date the information was gathered. When documents are produced, the documents shall be produced in an identified, organized manner that corresponds to each pertinent information request. A separate response must be provided for each incident. Each response, document or attachment must be clearly identified with the incident Sequence ID (SeqID) number.

- Provide a complete copy of the initial claim or notice document(s) that notified GM
  of the incident, excluding: (a) medical documents and bills, except those showing the
  cause of death or injury; (b) property damage invoices or estimates; and (c)
  documents related to damages.
- 2. Provide a copy of the Police Accident Report.
- 3. At your option, provide GM's assessment of the circumstances that led to the incident including GM's analysis of the claim and/or notice regarding allegations of a defect.

This letter is being sent to GM pursuant to 49 U.S.C. § 30166, which authorizes NHTSA to conduct any investigation that may be necessary to enforce Chapter 301 of Title 49 and to request reports and the production of things. It constitutes a new request for information. GM's failure to respond promptly and fully to this letter could subject GM to civil penalties pursuant to 49 U.S.C. § 30165 or lead to an action for injunctive relief pursuant to 49 U.S.C. § 30163. (Other remedies and sanctions are available as well.) Section 5(a) of the TREAD Act, codified at 49 U.S.C. § 30165(b), provides for civil penalties of up to \$5,000 per day, with a maximum of \$16,050,000 for a related series of violations, for failing or refusing to perform an act required under 49 U.S.C. § 30166. See 49 CFR 578.6 (as amended by 69 Fed. Reg. 57864 (Sept. 28, 2004). This includes failing to respond to ODI information requests.

If GM claims that any of the information or documents provided in response to this information request constitute confidential commercial material within the meaning of 5 U.S.C. § 552(b) (4), or are protected from disclosure pursuant to 18 U.S.C. § 1905, GM must submit supporting information together with the materials that are the subject of the confidentiality request, in accordance with 49 CFR Part 512, as amended (69 Fed. Reg. 21409 et seq; April 21, 2004), to the Office of Chief Counsel (NCC-110), National Highway Traffic Safety Administration, 1200 New Jersey Avenue, S.E., Washington, D.C. 20590.

Your response to this letter, together with a copy of any confidentiality request, must be submitted to this office by <u>June 8, 2007</u>. Please include in your response the identification codes referenced on page one of this letter. If you are unable to provide all of the information requested within the time allotted, you must request an extension from me at (202) 366-4238, no later than five business days before the response due date. If all of the information requested by the original deadline is unavailable, you must submit a partial response by the original deadline with whatever information then is available, even if an extension is granted.

If you have any technical questions concerning this matter, please contact Mr. Leo Yon at (202) 366-7028 or by fax at (202) 366-7882.

Sincerely,

Christina Morgan, Chief Early Warning Division

Office of Defects Investigation

this true morain

Enforcement

June 7, 2007

Ms. Christina Morgan, Chief Early Warning Division Office of Defects Investigation National Highway Traffic Safety Administration 400 Seventh Street, S.W. Washington, DC 20590

NVS-217ph DI07-044

Dear Ms. Morgan:

This is General Motors' (GM) response to your inquiry dated May 7, 2007 regarding certain death and injury incidents reported by GM in its light vehicle early warning report from 4th quarter of 2006.

GM's response is comprised of 29 CDs for the incidents that are the subject of DI07-044.

Attachment "A" includes instructions for navigating the CD. Each CD, on its face, is identified by the NHTSA Sequence ID number, the Manufacturer's Unique ID number and the year, make and model of the vehicle involved in the incident, e.g., 256 210873110 - 625130 and 2004 Chevrolet Suburban 1500. When the CD is launched, this identification number appears again along with all of the documents (including photographs and videos) on the CD listed under "Filename." The first document listed under Filename is an index with the Request and Responses, e.g., identified as 256 210873110 - 625130 \_00\_Request and Responses. The index is numbered 1 through 3 to correspond to Inquiries 1 through 3, which are repeated verbatim below. The index also details whether any documents responsive to each inquiry were located.

For example, the first two Inquiries and Responses in the index for the CD are as follows:

DI07-044 256 210873110 - 625130 2004 CHEVROLET SUBURBAN 1500

#### Request for Information:

Provide a complete copy of the initial claim or notice document(s) that notified GM
of the incident, excluding: (a) medical documents and bills, except those showing
the cause of death or injury; (b) property damage invoices or estimates; and (c)
documents related to damages.

Response: See Attached Document.

2. Provide a copy of the Police Accident Report.

Response: See Attached Document.

The remaining documents listed under Filename, reference the Manufacturer's Unique ID number along with the responsive Inquiry number. For example:

256 210873110 - 625130 \_01\_1 - is the first document responsive to Inquiry no. 1. 256 210873110 - 625130 \_02\_1 - is the first document responsive to Inquiry no. 2.

Product Investigations
Mail Code: 480-210-G11 • 30001 Van Dyke • Warren, MI 48090
DIO7-044 Response.doc



Letter to Ms. Christina Morgan DI07-044 Response June 7, 2007 Page 2 of 5

Your inquiries and our corresponding replies are as follows:

 Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.

Response: See Attached Document.

The table below lists the incidents that are the subject of DI07-044, by Reporting Category, Sequence ID, VIN and type of notice received by GM (as "notice" is commonly used, not as it is defined by 49 C.F.R. §579.4(c)). Incidents reported on GM's Early Warning Report Death and Injury worksheet fall into four categories: Lawsuit (LIT), NISM (Not In Suit Matters), Product Allegation Resolution (PAR), or Rumor (RMR). Lawsuit and NISM case types generally meet the §579.4(c) definition of "claim." PAR cases, in this context, refer to customer contacts in which an injury or fatality is alleged to have occurred as a result of a product defect, and are accompanied by a writing that may or may not meet the §579.4(c) definition of "claim" or "notice." Rumor incidents do *not* involve a written or verbal, implied or express allegation of a defect by a customer. Rather, rumor cases generally refer to incidents that GM learned of through the media, which were subsequently investigated further. As such, the document included in response to Inquiry 1 that can be found on the enclosed CD for the PAR and Rumor case listed in the table, may not be a claim or notice of the type generally defined as such by §579.4(c).

SEQUENCE ID	VEHICLE IDENTIFICATION NUMBER (VIN)	TYPE
30	1G6DP577770	NISM
40	1G6KD54Y05U	NISM
88	1G1AK52F657	RUMOR
91	1G1AK52F957	RUMOR
103	1G1AL15F877	NISM
116	1GNFG15T851	LIT
135	2G1WH52K349	NISM
137	2G1WH52K249	NISM
140	2G1WF52E159	LIT
155	1G1ND52J83M	NISM
221	2GCEC19T041	LIT
244	1GCHK29U23E	LIT
246	1GCHK23225F	LIT
256	1GNFK16T74J	LIT
257	3GNFK16T64G	RUMOR
273	1GNEC13V74J	LIT
274	1GNEC13TX5F	LIT
285	1GNDS13S822	LIT
295	1GNDT13S542	RUMOR
345	1GTEC14T74Z	LIT
360	1GKEC16Z14R	LIT
368	5GTDN136468	RUMOR
401	1G2ZG58B574	NISM
424	2G2WP552661	RUMOR
436	1G8AJ52F14Z	LIT
439	1G8AJ55F96Z	NISM

Letter to Ms. Christina Morgan DI07-044 Response June 7, 2007 Page 3 of 5

Provide a copy of the Police Accident Report.

Response: See Attached Documents.

At your option, provide GM's assessment of the circumstances that led to the incident including GM's analysis of the claim and/or notice regarding allegations of a defect.

To date, General Motors' investigation of the alleged defect has not included an assessment of the cause(s) of each incident responsive to this request. Some incident reports may not contain sufficient reliable information to accurately assess cause. Assessments of claims may be attorney work product and/or privileged. Therefore, information and documents provided in this response, if any, consist only of non-attorney work product and/or non-privileged material for incidents that have been investigated and assessed.

GM claims that certain information, in documents that are part of rumor, claim and lawsuit files maintained by the GM Legal Staff and its outside counsel, is attorney work product and/or privileged. That information includes notes, memos, reports, photographs, and evaluations by attorneys (and by consultants, claims analysts, investigators, and engineers working at the request of attorneys). GM is producing responsive documents from its rumor, claim and lawsuit files that are neither attorney work product nor privileged and withholding those that are attorney work product and/or privileged.

This response was compiled and prepared by this office upon review of documents retrieved by GM and does not include documents generated or received subsequent to the searches.

Please contact me at if you require further information.

de

Sincerek

Gay P. Kent Director


Product Investigations

Enclosures: 29 Discs Attachment A Letter to Ms. Christina Morgan DI07-044 Response June 7, 2007 Page 4 of 5


586

#### Attachment A Instructions for using CD Viewer

- Insert the CD into the CD ROM drive; the CD will open automatically.
- Click the "Run JPegger" button on the pop up window.



- The program will launch in the browsing mode, which is shown in the image below.
- You can use the down arrow key on your keyboard to browse through the images.



**Product Investigations** 


Mail Code: 480-210-G11 • 30001 Van Dyke • Warren, MI 48090

DI07-044 Response.doc



Letter to Ms. Christina Morgan DI07-044 Response June 7, 2007 Page 5 of 5

- Each image file may contain multiple pages. In the browsing mode use Next Page Icon (Ctrl +PgDn), Select Page Icon or Previous Page Icon (Ctrl +PgUp) to browse through all of the pages within an image file. (Note: Some image files may contain up to 80 pages)
- 6. By double-clicking on an image from the file list, a slide show will initiate, however, it will not automatically advance through the pages. Use Ctrl +PgDn or Ctrl +PgUp to browse through all of the pages within an image file. Left-clicking on an image, while in the slide show mode, will advance to the first page of the next image file.
- Right click on the image to see the image properties, as shown below. Image properties can also be used to view each page within the documents (Next page), or to view the next document within the file list (Next Image).
- If the image is difficult to view, the scale may be changed. Use F5, F6, F7, and F8 to alternate between scales that fit the screen, or are 50%, 100%, and 200% of the image's original size.



Product Investigations
Mail Code: 460-210-G11 • 30001 Van Dyke • Warren, MI 48090
DI07-044 Response,doc



## DI07-044 88 210872965 – 624620 2005 CHEVROLET COBALT

#### Request for Information:

1. Provide a complete copy of the initial claim or notice document(s) that notified GM of the incident, excluding: (a) medical documents and bills, except those showing the cause of death or injury; (b) property damage invoices or estimates; and (c) documents related to damages.

Response: See Attached Document.

2. Provide a copy of the Police Accident Report.

Response: See Attached Documents and Photographs.

3. At your option, provide GM's assessment of the circumstances that led to the incident including GM's analysis of the claim and/or notice regarding allegations of a defect.

Response: To date, General Motors' investigation of the alleged defect has not included an assessment of the cause(s) of each incident responsive to this request. Some incident reports may not contain sufficient reliable information to accurately assess cause. Assessments of claims may be attorney work product and/or privileged. Therefore, information and documents provided in this response, if any, consist only of non-attorney work product and/or non-privileged material for incidents that have been investigated and assessed.

Search Results Page 1 of 2

# TwinCities • com

Our Local Channels + News Business Sports Entertainment Living Archives Article Search Results (Articles older than 7 days) Archive Advanced Search | Archive Search Articles-last 7 days Go Note: Searching is always free. There is a \$2.95 fee to view the full-text of any article. Check out our Pricing Options. Searched for "woodville AND accident". Returning 3 articles of 3 found. If this is too many articles to browse, you may refine your search with additional terms: woodville AND accident Search Again Article 1 of 3; 333 words

#### 2ND TEEN DIES FROM CAR CRASH

#### OCTOBER INCIDENT STILL UNDER INVESTIGATION


Source: JOHN BREWER, Pioneer Press

A second passenger has died after a late October car crash in rural St. Croix County that remains under investigation died over the weekend at Regions Hospital in St. Paul, a hospital spokesperson said. The Albert Lea, Minn., resident and 2006 graduate had been in critical condition at the hospital since the Oct. 24 accident on County Road N. She was one of three occupan Chevrolet Cobalt that left the road about 8 p.m., went into a

Published on November 7, 2006, Page B4, St. Paul Pioneer Press (MN)

Article 2 of 3; 5532 words

#### **OBITUARIES**



Published on October 29, 2006, Page B8, St. Paul Pioneer Press (MN)

Article 3 of 3; 283 words

#### 1 TEEN KILLED, 2 INJURED IN CRASH

http://nl.newsbank.com/nl-search/we/Archives?s\_site=twincities&p\_multi=PD|&p\_produ... 11/15/2006

Search Results Page 2 of 2


#### GIRL WHO DIED WAS IN 10TH GRADE; FRIENDS IN CRITICAL CONE AFTER CAR HIT TREES


Source: KEVIN HARTER, Pioneer Press

A Woodville teen was killed and two of her friends were seriously injured Tuesday night when the car they were riding in left a run County roadway and struck several trees. Front-seat passenger of Woodville, was taken by rescue workers Hospital in St. Paul after the crash, St. Croix County Sheriff Dennis Hillstead said. The Baldwin-Woodville High School sophomore is dead at the hospital. She was riding in a 2005 Chevrolet Cobalt driven


Published on October 26, 2006, Page B1, St. Paul Pioneer Press (MN)

All content copyrighted and may not be republished without permission.





Document Number Override Officer's Opinion of Possible Contributing Circumstances **Driver Factors** · Vehicle Factors Highway Factors Unit Number Unit Number **Unit Number** Unit Number Unit Number Unit Number 2 3 4 5 1, 2) (3) 4, 5 1: (2) 30 (4) (3 സമതമാദ DOOO. DEOO O 678919 O N/A 7 8 (7) (8) 9 10 7 8 9 10 9 **6** (7) (8) (9) 10 DO (D) (D) (D) O N/A N/A N/A N/A N/A N/A Exceeding Speed Limit Speed Too Fast/Condition (1) Brake System Snow, Ice or Wet (2) (2) Narrow Shoulder (3.) Tues fail to Yield Right of Way Inattentive Driving Steering System Turn Signals (<u>3</u>) 3. (3) 3 3 **(3**) Low Shoulder Soft Shoulder (4) 4 (4) (4) (4) (<u>5</u>) Đ :s (5) (3) 3 Following Too Close Head Lamps Loose Gravel Improper Turn Left of Center Rough Pavement 6 Stop Lamps Tail Lamps 6 6 6) **(6) Ø** 7 Ō Œ D 7 Debris From Prior Accident (8) **(B)** 8) Disregarded Traffic Control . 8 Disabled in Prior Accident (D) Other Debris Improper Overtaking Unsafe Backing Sign Obscured or Missing 9 9` (9) ூ **(1)** (9) Other Disabled .10: iq JQ. JP. ÍÌ Narrow Bridge 10 Mirrors (11) 11: Failure to Have Control 30 Suspension System IJ TU Construction Zone Œ Visibility Obscured Other 12 Driver Condition 12 120 12 Other 12 13 Physically Disabled (13) Other Time Arrived (Military Time) Time Notified OFFICER INFORMATION Date of Report Date Notified (Military Time) MONTH DAY YEAR Last HINOM DAY YEAR HOUR MIN. HOUR MIN. ) Jan Jan ") fcb Feb Law Enforcement Agency Address 00000 ) Mar 0000 ◯ Mr OW OO 00000 Œ ∧pr  $\mathbf{\Phi}$ 0 City & State 719 **②②②**② 3 **②②②② ②** ② 3 Œ 30 (3D (3D 3 127 **( (1)** (1) **(4) (1)** Phone Number **©**©0 **(5)** (5)(5)(5) ூ (3) © 7) (I) (1) **(D**) **(6**) **(5**) **©**  $\bigcirc$  0 $\alpha$ T. (T) 0 (Z) 2 (7) Enforcement Agency Officer ID # Agency # Nov (8) **(B)** Ē 8 8 ⊃ Nov Truck & Bus Accident Information (This Section Must Be Completed for Each Truck or Bus Involved in this Accident.). 器类型Hazardous Material Information 图像 When To Use This Section: Did the accident involve:... Part A A truck with at least two axles and six tires? · Hazardous Material Class Numbers (1-2digit): Y) (N) A truck with a hazardous materials placard? A bus designed to carry 16 or more persons, including the driver? Hazardous Material "UN" Numbers (4 digit): STOP! If <u>all</u> the responses to Part A are "NO" do not complete this Truck & Bus Accident Information Section. If there are <u>anv</u> "YES" answers, continue to Part B. (T) (E) Hazardous Material Placard Displayed? Hazardous Cargo was Released? Any person who was fatally injured? (Y) (N) List the Hazardous Material(s) by Name in this Load: Any injured person who required transport for immediate medical treatment? One or more vehicles that had to be towed from the scene as a result of the accident? List the Name(s) of Released Hazardous Material(s): STOP! If <u>all</u> the responses to Part B are "NO" do not continue. If there are <u>any</u> "YES" answers, please complete this Truck & Bus Accident Information Section . . . Carrier Identification Numbers Source: Carrier Information ○ Vehicle Side Shipping Papers
Trip Manifest œ o Interstate Carrier? (Y) N ICC MC IC Driver Carrier Name Carrier Address C Log Book LBS Total # of Axies Gross Vehicle Weight Rating Vehicle Information Vehicle Configuration Cargo Body Type (9) Unknown Heavy Truck Truck Tractor 10 undeum truck 2 ades, 6 tues SEQUENCE OF EVENTS FOR THIS VEHICLE ①②③① Ran off Road ①②③④ Jackknife ① ② ③ ① Collision Involving Motor Vehicle in Transp. ① ② ③ Collision Involving Parked Motor Vehicle 10 (2) (3) (4) Overtum (Rollover) ① ② ③ ① Collision Involving Train (1) (2) (3) (4) Collision Involving Pedalcycle .2: 3 4 Downhill Runaway DOOD Cargo Loss or Shift DOOD Explosion or Fire ① ② ① ① Collision Involving Animal ① ② ① ① Collision Involving Fixed Object **@** (1) (2) (3) (3) Collision Involving Other Object (1) (2) (3) (4) Collision Involving Pedestrian 1 2 3 1 Other 



AT APPROXIMATELY 0015 I SPOKE WITH STAFF FROM REGIONS HOSPITAL BY PHONE. THEY SAID HAD BEEN PRONOUNCED DEAD ON 10/24/06 AT 2318. THEY SAID WAS UNCONSCIOUS, INTUBATED, AND IN CRITICAL CONDITION. THEY SAID WAS UNCONSCIOUS AND IN CRITICAL CONDITION. THE VEHICLE WAS REMOVED FROM THE SCENE BY JERRY'S TOWING. DEPUTY KOENIG FOLLOWED THE VEHICLE TO THE SHERIFF'S DEPARTMENT IMPOUND LOT. DEPUTY KOENIG AND I THEN INVENTORIED THE VEHICLE. TROOPER TRAYNOR HAD REQUESTED THAT I CONTACT THE VEHICLE OWNER ASK HIM TO CONSENT TO HAVING THE "SDM" REMOVED FROM THE VEHICLE. TROOPER TRAYNOR ADVISED THAT THE "SDM" COULD POSSIBLY HOLD DATA THAT WOULD HELP DETERMINE WHY THE AIRBAGS HAD NOT DEPLOYED. BY PHONE. ON 10/25/06 I SPOKE WITH SAID THAT HE WOULD MEET WITH ME THE NEXT DAY TO SIGN THE CONSENT FORM. ON 10/26/06 I PHONED AGAIN TO ARRANGE A TOLD ME THAT HIS INSURANCE COMPANY'S LAWYER HAD TOLD HIM ONLY TO SIGN THE CONSENT FORM IF THEY WERE ALLOWED TO BE THERE WHEN THE SDM WAS REMOVED AND WERE GIVEN ACCESS TO THE DATA ON IT. I TOLD THAT I WOULD RELAY THEIR REQUEST TO TROOPER TRAYNOR. IF THE VEHICLE HAD EVER BEEN INVOLVED IN AN ACCIDENT BEFORE. SAID A DEER HAD "BRUSHED" THE REAR DRIVER'S SIDE ONCE BUT THERE WAS NO DAMAGE. SAID OTHER THAN OIL CHANGES THE ONLY TIME THE VEHICLE HAD BEEN WORKED ON WAS AT JACOBSON CHEVROLET, 1860 10 AVE BALDWIN WI 54002, 715-684-4600, FOR A RECALL CAMPAIGN. BELIEVED THE RECALL WAS FOR SOMETHING TO DO WITH THE AIRBAGS AND MAYBE A WINDSHIELD WIPER SWITCH. SAID NONE OF THE WARNING LIGHTS ON THE DASH HAD BEEN ILLUMINATED PRIOR TO THE ACCIDENT. I SPOKE WITH TROOPER YOUNG BY PHONE. TROOPER YOUNG ADVISED THAT THEY WOULD MOST LIKELY JUST GET A WARRANT FOR THE SDM. HE ALSO REQUESTED A FULL COPY OF THE ACCIDENT REPORT FOR THE RECONSTRUCTION. ON 10/26/06 I SPOKE WITH RONALD DRAHOS BY PHONE. RONALD SAID THAT HE WAS AFFILIATED WITH THE TRANSPORTATION RESEARCH CENTER AT INDIANA UNIVERSITY WHO WAS UNDER CONTRACT WITH THE NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION. RONALD SAID THEY INVESTIGATED TRAFFIC CRASHES OF "SPECIAL INTEREST". RONALD SAID THIS WAS A CRASH OF SPECIAL INTEREST BECAUSE THE AIR BAGS HAD ALLEGEDLY NOT DEPLOYED IN A SITUATION WHEN THEY SHOULD HAVE. I ARRANGED FOR RONALD TO EMAIL ME A FORMAL REQUEST FOR THE INFORMATION THEY WISHED TO ATTAIN (ATTACHED). ON 10/27/06 I SPOKE WITH REGIONS HOSPITAL STAFF BY PHONE. THEY SAID THAT WERE STILL IN CRITICAL CONDITION AND NEITHER WAS CONSCIOUS. I ALSO SPOKE WITH THE RAMSEY COUNTY MEDICAL EXAMINERS OFFICE. THEY SAID THAT AN AUTOPSY HAD BEEN DONE

ON AND THEY WOULD SEND US A COPY OF THE REPORT WHEN IT WAS COMPLETED IN 6 TO 8


CLEAR.

WEEKS.

ON 10/24/06 AT 1957 I DEPUTY ERIC JOHNSON WAS DISPATCHED TO RESPOND TO THE AREA OF 1248 CTH N FOR A SINGLE VEHICLE ACCIDENT WITH MULTIPLE PERSONS INJURED. WI STATE TROOPERS LOONSFOOT, SHILTS, AND DEPUTY SOMMERS ALSO RESPONDED.

ON ARRIVAL I SAW THE ABOVE VEHICLE IN THE SOUTH DITCH FACING SOUTH. THE VEHICLE HAD SEVERE FRONT END DAMAGE. THERE WAS A LARGE CLUMP OF TREES WITH DAMAGED BARK IN FRONT OF THE VEHICLE. THERE WAS A LARGE TREE BRANCH/TRUNK LYING ACROSS THE TOP OF THE VEHICLE. THE TROOPERS WERE ALREADY ON SCENE AND ASSISTING THE THREE FEMALE OCCUPANTS. ONE OCCUPANT WAS SEATED IN THE DRIVER'S SEAT, ONE IN THE FRONT PASSENGER SEAT, AND ONE IN THE REAR DRIVER'S SIDE SEAT. THE VEHICLE AIRBAGS WERE NOT DEPLOYED AND THE SEATBELTS DID NOT APPEAR TO HAVE BEEN USED.

I HELD C-SPINE ON THE I	DRIVER UNTIL EMS ARRIVED. THE DRIVER WAS SITTING ON THE FLOOR IN
FRONT OF THE DRIVER'S	SEAT WITH HER LEGS ENTRAPPED UNDER THE DASHBOARD. THE DRIVER
APPEARED TO BE SEVER	ELY INJURED BUT WAS CONSCIOUS. THE DRIVER SAID HER NAME WAS
. I ASKED	WHAT HAD HAPPENED. MAJOR SAID SHE DIDN'T KNOW, EMS ARRIVED AND
STARTED EVALUATING	WAS LATER IDENTIFIED BY A WI PICTURE INSTRUCTION
PERMIT LOCATED IN THE	VEHICLE.



THE BACK SEAT PASSENGER

WAS LATER IDENTIFIED BY A MN PICTURE DRIVER'S
LICENSE LOCATED IN THE VEHICLE.

WAS BREATHING BUT UNRESPONSIVE.

TORSO WAS LYING ACROSS THE
REAR BENCH SEAT FACE UP WITH HER HEAD TOWARDS THE PASSENGER SIDE.

FIRE AND EMS REMOVED THE OCCUPANTS FROM THE VEHICLE. WAS TRANSPORTED BY GROUND AMBULANCE TO REGIONS HOSPITAL IN ST PAUL. WAS TRANSPORTED BY GROUND AMBULANCE TO THE HUDSON MEDICAL CENTER AND AIR LIFTED FROM THERE TO REGIONS HOSPITAL. WAS AIR LIFTED FROM THE SCENE TO REGIONS HOSPITAL.

AND

TOLD ME THAT THEY HAD BEEN EASTBOUND ON CTH N. THEY SAID THERE HAD
BEEN TWO OR THREE VEHICLES IN FRONT OF THEM.

SAID WHEN THEY CAME UPON THE
VEHICLE IN THE DITCH THEY THOUGHT IT WAS AN OLD ACCIDENT. THEY SAID THE CARS IN FRONT OF
THEM HADN'T STOPPED BUT AS THEY WENT BY THEY NOTICED SMOKE COMING FROM UNDER THE
HOOD OF THE VEHICLE. THEY SAID THEY TURNED AROUND AND APPROACHED THE VEHICLE. THEY
SAID AS THEY APPROACHED THE VEHICLE THEY HEARD SCREAMING AND THEN SAW THE THREE
OCCUPANTS. THEY SAID AT THE SAME TIME

CAME FROM HER HOUSE AND THEY
YELLED FOR HER TO CALL 911.


SAID NONE OF THE OCCUPANTS CHANGED POSITIONS IN THE
VEHICLE BEFORE THE POLICE ARRIVED.

SAID SHE HAD HEARD THE ACCIDENT BUT HADN'T SEEN IT. SAID THAT WHEN SHE WENT OUTSIDE TO SEE WHAT HAD HAPPENED THE GUYS TOLD HER TO CALL 911.

DEPUTY SOMMERS TOOK DIGITAL PHOTOGRAPHS OF THE SCENE. WI STATE TROOPERS TRAYNOR AND YOUNG RESPONDED TO RECONSTRUCT THE ACCIDENT.

I NOTIFIED S PARENTS AND HUSBAND OF THE ACCIDENT. I NOTIFIED S PARENTS OF THE ACCIDENT. WITH THE ASSISTANCE OF THE ACCIDENT.

I WAS ABLE TO



NHTSA-MARKEY-000135

Entered By: Eric J Johnson, On 10/27/2006 10:53:46 PM Edited By: Eric J Johnson, On 10/27/2006 11:35:48 PM

Title: FATAL MOTOR VEHICLE ACCIDENT

#### ST CROIX COUNTY SHERIFF'S DEPARTMENT 1101 CARMICHAEL RD HUDSON WI 54016 (715)381-4320

Entered By: Eric J Johnson, On 11/9/2006 10:41:37 PM

Title: SUPPLEMENTAL TO 06-9697

DEPUTY ERIC JOHNSON

SUPPLEMENTAL TO 06-9697

DECEASED:

ALBERT LEA MN

HAD BEEN STAYING AT BELOW ADDRESS SINCE LATE AUGUST 2006

WOODVILLE WI

ON 11/05/06 I WAS ADVISED BY STAFF AT REGIONS HOSPITAL THAT HAD BEEN PRONOUNCED DEAD AT REGIONS HOSPITAL ON 11/04/06 AT 1019 HOURS.


I HAD DISPATCH SEND THE FATALITY NOTIFICATION TTY. I ALSO AMENDED THE MV4000 AND MOTOR VEHICLE FATALITY SUPPLEMENT REPORT TO REFLECT THE FATALITY.

CLEAR.


			2					
MOTOR VEHICL Wiscorein Department of Transport MV3430 801	E FATAL SU	PPLEMENT REPORT			1. Document Number (From MV4000)	129330	1	
men and American services		ACCIDENT INFO						
2. Accident Date (No-Day-Yd)	3. No. of Travel Lance	4. Time Ambutance NOTIFIED	5. Time Ambulano	on Anhead at SCENE		rived at HOSPITAL	1	
10-24-06	3	7:5°) AM	8:10	C €	11:19		AM AM	
7. Roadway Surface Type		9. Special Jurisdiction	10. Relation		11, Trafficway F	low	-VM	
1 Concrete	Profile	0 No Special Jurisdiction	1 On Roadwa		1 Not Physically		5.0	
2 Blacktop (Bituminous)	1 Level	1 National Park Service	2 Shoulder			(Two Way Traffioway)		
3 Brick or Block	2 Grade	2 Military	3 Median		2 Divided Highwa	y, Median Strip	ρ	
4 Slag, Gravel or Stone	3 Hillorest	3 Indian Reservation	4 Roadside		(Without Traffic			
5 Dirt	4 Sag	4 College/University Campus	5 Outside Rig		3 Divided Highwa		•	
8 Other		5 Other Federal Properties	6 Off Roadwa		(With Traffic Bar			
[5]			Location Un	known	4 One Way Traffic	way r	7	
[a]	[2]		7 in Parking L 8 Gore	ane [5]	* "		1	
	· · ·	VEHICLE INFOR						
			14. Fire Y/N		40 E-0	d Travel Speed		
12. Special Use	100	13. Emergency Use Y/N See s.340.01(3),	14. FRO 1/M		15. Esumaia	I rave Speed		
O No Special Use	Unit 1	346.03 Wis. Stats. Unit 1	1 100	Unit 1				
1 Taxi		N	i	N.	Unit 1			
2 Vehicle Used as School E	RUS				50	HAW C		
3 Vehicle Used as Other Bu	s Unit 2	Unit 2	***	Unit 2	Unit 2			
4 Military						ş: 9	3	
5 Police	Unit 3	Unit 3		Unit 3	Unit 3		-	
6 Ambulance 7 Fire Truck				· 1.	CARLO .	5°		
						·		
		SURVIVING DRIVER IN	FORMATION					
Unit 1					Ejected	I Datasal	J	
28/200-22					YA	N/A	$\mathbf{L}$	
19. Alcohol Test	21. Alcoho	ol Test Type - Circle One	22. Drug Test	100	23. Drug T	est Type - Circle	e One	
Given Y/N N	1. Evident	ial Test - Circle One	Given Y/N	N	Blood			
20. Alcohol Test Results-Cin	1A E	Breath; 1B, Blood; 1C, Urine		00000	o Utine			
	2 Prelimir	nary Breath Test (PBT)	24. Drug Test F		One Sing			
	suits 3. Behavio		1. No Drugs Re	A-1				
2. Test Refused			2. Drugs Repor				_	
3. Results Unknown		Alcohol Sensor (PAS)	3. Tested, Resu	its Unknown				
		<b>MD</b>		• • •				
Unit 2 NAME Flest		M . Last			- Flored	☐ Eddicated ☐	$\neg$	
OIM Z				:	Ejected Y/N	Y/N		
Voohol Test	Alcohol Te	st Type - Circle One	Drug Test	<u> </u>	Drug Test	ype - Circle Or	10	
Siven Y/N			Given Y/N	1 1	Blood			
	- 44.0		1970	ب	7 .		2.4	
Vicohol Test Results - Circle	CIRE	Total Treat (Total)	Drug Test Resu		, UNITE			
. Actual-Give Results Re-	STATE I	nary Breath Test (PBT)	1. No Drugs Rep	ported				
2. Test Refused	3. Behavio		2. Drugs Report	ted - Specify				
B. Results Unknown	4. Passive		3. Tested, Resul					
	5. Observe	d' '						
NAME Fint		VO Lest			Sut C	Extricated	<del></del> -	
Unit 3				e.	Ejected Y/N	Y/N		
Voohol Test	Alcohol Te	st Type - Circle One	Drug Test	<del></del>	Drug Test 1	ype - Circle On	10	
Siven Y/N			Given Y/N	1 .	Blood		_	
	44 P				. Urine		-	
Voohol Test Results - Circle	CAR.		Drug Test Resul	Charles and Charles State Control of the	CHIE			
. Actual-Give Results   Bes	ante l	ary Breath Test (PBT)	1. No Drugs Rec	ported				
. Test Refused	3. Behavio		2. Drugs Report	ed - Specify	1	37.3		
. Results Unknown	4. Passive		3. Tested, Flesul		. 1 . 1. 1.			
	5. Observe							
		FATALITY INFORM	ATION				_	
25. Name - First	. м			. Extricated Y/N	28. Date of Death	29. Time of Dec	nith	
				ED	- loud	. 10		
			N	171 1	10/24/06	11:18.	<b>#</b>	
•			<u> </u>	أسانات		1	<u> </u>	
							AM PM	
							PM	
		74				*	AM	
							PM	
O. Officer Completing Report - Print	Name	31. Officer ID No .   32. Ent	orcement Agency No	ime		53. Report Date		

# \* Amended 11-09-06, fatality #2 added

MOTOR VEHIC	EEAT	CAL CILI	DDI EMENT	PEDADT			1. Document Numbe	
Misconsin Department of Trans	Sportation	AL SU				2.5. 0	From MV4000) 8	929339
			ACC	CIDENT INFO	RMATION			
2. Accident Date (Mo-Day-Yr) 10-24-06	a No. of	A Lanes	4. Time Ambulance No.	TIFIED AM	5. Time Ambulan 8:1	SOS is been A A A P T T T T T T T T T T T T T T T T	11 0.11	MA LATTRECH IN DON'TH
7. Roadway Surface Type 8. Roadway 1 Concrete 2 Blacktop (Bituminous) 3 Brick or Block 2 Grade		Special Jurisdiction     No Special Jurisdiction     No Special Jurisdiction     National Park Service     Military		10. Relation To Roadway 1 On Roadway 2 Shoulder 3 Median		11. Trafficway Flow 1 Not Physically Divided (Two Way Trafficway) 2 Divided Highway, Median Strip		
4 Stag, Gravel or Stone 5 Dirt 8 Other	3 Hillon 4 Sag	est	3 Indian Reservation 4 College/University 5 Other Federal Programmes	niversity Campus 5 Outside Right of Way		(Without Traffic Barrier) 3 Divided Highway, Median Strip (With Traffic Barrier)		
. a		<b>a</b>		0	Location Ur 7 in Parking L 8 Gore		4 One Way Traffi	cway 1
				ICLE INFOR				
12. Special Use			13. Emergency Us See s.340.01(3),	Y/N	14. Fire Y/N		15. Estimat	ed Travel Speed
0 No Special Use 1 Taxi 2 Vehicle Used as School	Bus L	Unit 1	346.03 Wis. Stats.	N		Unit 1	Unit 1	H9M C
3 Vehicle Used as Other 4 Military 5 Police	Bus	Unit 2 Unit 3		Unit 2	***	Unit 2	Unit 2	<u> </u>
6 Ambulance 7 Fire Truck	Ľ	June 3		Unit 3		Unit 3	Unit 3	
		•	SURVIVIN	G DRIVER IN	FORMATION			
Unit 1						•	17. Ejected Y/N	N Extracted Y/N
19. Alcohol Test Given Y/M			ol Test Type - Circle ial Test - Circle One		22. Drug Test Given Y/N	N	23. Drug 1 Bloom	est Type - Circle One
20. Alcohol Test Results-0	Sircle One		reath; 1B. Blood; 10		24. Drug Test F	Results - Circle	One Urino	•
1. Actual-Give Results	Results		vary Breath Test (PE	37) ^	1. No Drugs Re			
2. Test Refused		3. Behavio	7-777-0	~ .	2. Drugs Repor		· · ·	
3. Results Unknown		5. Observe		s) 	3. Tested, Resu	alts Unknown	•	
Unit 2			M . Led	*			Elected Y/M	Edricated Y/M
Alcohol Test			st Type - Circle One		Drug Test		7	Type - Circle One
Given Y/M Alcohol Test Results - Circ	te One		al Test - Circle One reath; 1'B.'Blood; 10	1144	Given Y/N Drug Test Resu		Blood Urine	9
1. Actual-Give Results			ary Breath Test (PB	m 1	1. No Drugs Re		•	
2. Test Refused	Document	3. Behavior	naÍ .	2	2. Drugs Repor			
3, Flesuits Unknown		4. Passive . 5. Observe	Alcohol Sensor (PA d		3. Tested, Resu			
Unit 3			Al Lest	,			Elected .	Extricated Y/N
Alcohol Test Given Y/N			st Type - Circle One al Test - Circle One		Orug Test Siven Y/N		Drug Test 1 Blood	ype - Circle One
Alcohol Test Results - Circ		1A. Br	eath; 1B. Blood; 10 ary Breath Test (PB	. Urine	Drug Test Resu		Urine	50 W
	easurts I	3. Behavior			. No Drugs Reg		7	
2. Test Refused 3. Results Unknown			Moohol Sensor (PAS		Drugs Report	and the same of th	. 1 - 2 - 7 :	
a. Postuits Univiowii		5. Observed		' '	, restou, riesu	re orkinani -		
25. Name - First	м		FATA Lest	LITY INFORM		7. Extricated Y/N	26. Date of Death	29. Time of Death
1.					N	V	10/24/06	11:18
2.					N	N	11-04-06	10:19
3.					$\overline{\sqcap}$	П		AM PM
30. Officer Completing Report - P	int Name	1	31. Officer ID No	32. Ento	comert Agency N	erne V C C		83. Report Date



	Amended Document    On Emergency		8939106 _		
	Wisconsin Motor Vebicle			Document Number O	verride
	Accident Report	Time of Accide	ent	#It & Run 9339	loit#
$\Gamma$	INSTRUCTIONS County MUN/TWP	Accident Date (Military Time	e) Total Number	Government Property Y M Fire (Narrative) Y N	Sheet No.
000	Please use a  Black link Pen  Or #2 Bross	Feb 3406 5		Photos Taken (Narrative) . Y N	Of
ð	or #2 Pencil.	Mar (0) (0) (0) (0) (0) (0)		Trailer or Towed (Narrative) Y N Truck or Bus (Last Page) Y N	
Š	Mark Areas as shown: (2) (3) (3) (4) (4) (4) (4) (4) (4) (4) (4) (4) (4		0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	Load Spillage (Y. NO) Construction Zone	16
90,700	3 (3)	June (3) (3) (3) (3) (3) (3) (3) (3) (3) (3)	(3) (3) (3) 3/(3) (5)	Names Exchanged 9 Y (N)	
Police No.	Ø 20 € 10 € 10 € 10 € 10 € 10 € 10 € 10 €	Aug (5) (5) (5) (5) 5	(9) (9) (9) (9)	ACCIDENT LOCATION	St
£	Reportable DO DO	■0α 20 (2) (£	නගනනනන	<ul> <li>Public Highway, Intersection</li> <li>Public Highway, Non-Intersection</li> </ul>	section =
		) Nov 8 8 8 8 8		Parking Lot     Private Property or Road	
7.5	LATTTUDE (GPS) Degrees:	nutes: Seconds:	LONGITUDE (GPS) Degrees: 13	Wayne.	Seconds:
Tion S	ON Hwy No. and / Street Name	Estimated OF		Hwy No. and / Street Name	
de: m	HO Rouse# O Fire# C3 Other		Agency Space		Special Study 119
11:5		17	18		(D) (D) (D) (D)
=:		mber of Occupants Direction of Travel (Before the Accident)	Unit Number Unit	type was number or occupants	(Before the Accident)
: NO.	(9/9)79/9) (5/9)70 Out	0 22 (25 (35 (35 (35 (35 (35 (35 (35 (35 (35 (3	①②②②③ ①② ⑤③⑦⑦④ ⑤⑥		(W) (E)
) j	2: (9) (0) 2: (2 Speed OPERATOR Last Fin	x MT	Speed OPERATOR Last	First .	ML S
E	Limit NAMI		Limit NAME 25		
Z.	ADDRESS Street & Number		ADDRESS Street & Number		_
	① 26 ③ City & State	ZIP Phone Number ( )	② 26 ③ City & State	ZIP Phone Nu	mber ( )
	(6) 27 (6) 24	. 24	① 27	25	
	(6) Driver's License Number	State Exp. Year	(6) Differs Diceise Multiper	State	Exp. Year
	Date of Birth	Class Endorse	Date of Birth	,*0) Cla	
- 1	On Duty D Police Sex M.	Operating (Mark Only One) (Mark All That Apphy)	On Duty (P) Police	Sex M Operating (Mark On	
	Accident © EMT/First Responder © Fire Fighter CMV (Y)	Classified: 40 (20 (20 (20 (20 (20 (20 (20 (20 (20 (2	Accident (E) EMT/First Responder	CMV (Y) Classified: (( B)	
1	Severity SEAT SAFETY AIRBAG		Severity SEAT SAFETY		
	ON Position Equipment Deployed	(1) Not Applicable (4) Partially Ejected	OD OD Position Equipment	Deployed Ti Nox Applicab	
	A) (2) Non Dep (5) Not Appl	icable (3) Touth Liened	(A) (B)	Non Deployed (2) Not Ejected (3) Not Applicable (3) You'll Ejected	رية: Uninown علم
5	TRAPPED 13 D Not Applicable D Trapped Extric		TRAFFED : 39 (0) Not Applicable	(5) Unknown (5) Unknown	Medical 1 (Y)
7	EXTRICATED ② Not Trapped ④ Trapped/Not E	atricated Transport (B)	EXTRICATED 2 Not Trapped  Not Trapped  I last Name	Trapped/Not Extricated	Transport N.
ľ	Same (3) (30) 46		Same (Y) (N) +6		
- 1	Street Address	4	Street Address	8	=
Ī	City & State	ZIP Phone Number ( )	City & State	ZIP Phone N	umber ( )
-	Year of Vehicle Make Model		Year of Vehicle Make	Model Body Style	Color
Oate V	5() 51 52 Vehicle ID Number		50 51 Weblide ID Number	52 53	
5	35		15		( - V - V -
	icense Plate Number	57 58 (4) 5	License Plate Number	Plate Type	State Exp. Year
	Olicy Holder's Name		Policy Holder's Name		1 2 3 SOCO
2	is skry insurance Company	Stat #	iability Insurance Company	Stat. #	3330
[	Occupant NAME Last	First , M.L. , E	Date of Birth Sex	Severity SEAT SAFETY  ON: Position Equipment	AIRBAG 1. Deployed com
	Unit Number 60 ADDRESS Street & Number	City & State	71P	Ø   1 3	Non Deployed
L	ET TO TO			© 70 71 72 75 A	Not Applicable     Unknown
	S Operator Yes 1. Not Applicable 4) 1	TRAPPED/ Partially Ejected EXTRICATED I Not Ap	Trapped/Extricated oplicable 4 Trapped/Not Extricated	Medical Agency Space X	= -
F	No S Not Ejected 3	Inknown (2) Not To		EMS Number	
	MY4000 899 □■○○·				=



MV4000 899

**EMS Number** 

# COLLISION ANALYSIS & RECONSTRUCTION REPORT



EAU CLAIRE POST CASE #
ST. CROIX COUNTY CASE #

**COLLISION DATE: 10-24-2006** 

LOCATION: CTH N East of North Skyline Drive ST CROIX COUNTY, WI

PREPARED BY: KEITH A. YOUNG

TROOPER
TECHNICAL RECONSTRUCTION UNIT
WISCONSIN STATE PATROL ACADEMY
608-269-2500

REPORT DATE: February 14, 2007

### **TABLE OF CONTENTS**

INFORMATION UTILIZED FOR COMPLETION OF REPORT	3
SYNOPSIS	4
OBJECTIVE	4
COLLISION SCENE	4
COLLISION SEQUENCE	5
SERVICE BULLETIN	6
VEHICLE INSPECTION	6
FORENSIC SCENE MAPPING	7
SENSING AND DIAGNOSTIC MODULE	7
EXEMPLAR VEHICLE MEASUREMENTS	8
SPEED ANALYSIS	9
VEHICLE FACTORS	9
HUMAN FACTORS	10
ENVIRONMENTAL FACTORS	10
WEATHER	
INVESTIGATIVE SUMMARY	11
APPENDIX	12
TROOPER TRAYNOR'S REPORT	ATTACHED

#### INFORMATION UTILIZED FOR COMPLETION OF REPORT

- Wisconsin Motor Vehicle Accident Report MV4000 completed by Deputy Eric Johnson.
- 2. Narrative Reports by St Croix County Sheriff's Department Deputy Eric Johnson.
- 3. Narrative Report by Trooper William Traynor.
- Forensic Mapping Measurements by Troopers Keith Young and William Traynor.
- Scene Photographs by Deputy Sommers and Trooper Young.
- SDM Photographs at St Croix County impound lot by Trooper Young.
- 7. Moon Position Data, U.S. Naval Observatory.
- 8. Weather Conditions Data, Weather Underground.
- Vetronix CDR Report for 2005 Chevrolet Cobalt VIN; 1G1AK52F657



10. Interview by Deputy Johnson with:



11. Wisconsin Department of Transportation Records for



#### SYNOPSIS

On October 24, 2006, a Chevrolet Cobalt driven by was eastbound on CTH N just east of North Skyline Drive. The vehicle traveled onto the south shoulder and into the south ditch. The vehicle then launched off of the west edge of a driveway and became airborne. The vehicle landed and traveled through the ditch before striking a telephone junction box and two trees. The vehicle then rotated clockwise coming to rest in the south ditch facing south.

The right front seat passenger and left rear seat passenger later died as a result of injuries they received in the crash.

#### OBJECTIVE


The primary objective of this analysis is to evaluate the speed and positions of the vehicle during the collision sequence. A study of the vehicle, human or environmental factors including safety belt use and airbag non-deployment will also be performed.

#### COLLISION SCENE

The crash scene is located on CTH N east of Skyline Drive in the Township of Kinnickinnic. This is a rural area of St. Croix County. The pavement in the area of the crash is traveled asphalt flanked by gravel shoulders. Traffic traveling east on CTH N has a downgrade of approximately 0.05 percent.

Upon my arrival on scene I viewed the scene with Deputy Mark Sommers and Trooper William Traynor. The roadway leading up to the crash scene was inspected for any indication as to why the vehicle left the road. The first evidence that could be observed was gravel from the shoulder scattered onto the eastbound lane approximately 195 feet west of the driveway at 1237 CTH N. This was most likely caused by the tires of the


they left the roadway. There were rolling tire marks in the south ditch that lead up to the edge of the driveway. The vehicle then struck the sloped driveway embankment and vaulted approximately 59 feet through the air. The vehicle landed and traveled another 82 feet before striking a telephone junction box. The vehicle then traveled an additional 46 feet before striking a grouping of two trees, and rotating approximately degrees. The vehicle came to rest just north of the trees, facing south in the south ditch.



-Page 4 of 12 -

#### COLLISION SEQUENCE

As the vehicle traveled down a slight grade her vehicle went onto the south shoulder and into the south ditch. When the vehicle approached the driveway at house number 1237 it launched off of the west edge of the driveway and was airborne for approximately 59 feet. The vehicle landed and traveled approximately 82 feet before striking a telephone junction box and knocking it down. The vehicle then traveled another 46 feet through some brush before striking two larger trees. The vehicle then rotated clockwise approximately 94 degrees while traveling another 14 feet before coming to rest.



this wood a month in Citizen

- Page 5 of 12 -

#### SERVICE BULLETIN

On October 27, 2006, I obtained a printout of a General Motors document ID# 1686453 (A/C system wiring or dual stage airbag module wiring # 05034A - (07/22/2005)) for a 2005 Chevrolet Cobalt. I also obtained a copy of the GM Vehicle Inquiry System Summary for the 2005 Chevrolet Cobalt VIN: 1G1AK52F657 These reports were forwarded to State Patrol Inspector George Wright. Inspector Wright reviewed the two GM reports to determine if the appropriate repairs were made. Inspector Wright advised me that the air conditioning wiring repair was the correct repair for this vehicle and that the reports indicate that the air conditioning wiring repair was done. Inspector Wright further advised that the dual stage airbag module wiring was not required to be changed on this vehicle. (See Inspector Wright's report).

#### VEHICLE INSPECTION

#### 2005 CHEVROLET COBALT VIN 1G1AK52F657

DRIVER:

On October 24, 2006, while at the scene I examined the vehicle and the following observations were made:

There was heavy frontal contact damage concentrated on the right side and induced damage to the roof and passenger side. Emergency medical services (EMS) had removed the right front passenger door and cut both A-pillars to extricate the front seat occupants.



#### Tires

Left Front tire, P195 60 R15 Continental, tire flat 0/32 tread depth Right Front tire, P195 60 R15 Continental, 1/32 – 2/32 tread depth Left Rear tire, P195 60 R15 Continental, 6/32 – 6/32 tread depth Right Rear tire, P195 60 R15 Continental, 5/32 – 6/32 tread depth

#### Seatbelts

Driver seat belt retracted, no signs of use
Right Front passenger seat belt retracted, no signs of use
Left Rear passenger seat belt retracted, no signs of use
Center Rear passenger seat belt retracted, no signs of use
Right Rear passenger seat belt locked retracted, no signs of use


On December 11, 2006, I met with Robert Wozniak an engineer from Skogen Engineering at the St. Croix County impound lot to inspect the vehicle. The fuse block was examined, it was determined that fuse number 28 for the audio system was blown. It was also confirmed that the airbag wiring procedure noted in service bulletin #05034A had not been done.

\*\* Note: As mentioned in the above section titled Service Bulletin, the airbag wiring procedure did not apply to this vehicle.


- Page 6 of 12 -

#### FORENSIC SCENE MAPPING

On October 24, 2006, with the assistance of Trooper William Traynor the crash scene was mapped with the State Patrol's Geodimeter 610 Total Station. Detailed measurements of the scene were taken locating roadway and lane edges, tire marks, a utility box and tree as well as the final rest position of the vehicle involved in the crash. The measurements obtained using the total station were then used in Crash Zone, a Computer Aided Drawing (CAD) program to produce a forensic map of the crash scene.



On November 6, 2006, Trooper Traynor and myself went to the St. Croix County Impound Lot to measure the damage profile of the vehicle. Using the State Patrol's Geodimeter 610 Total Station, measurements of the vehicle were taken to determine the amount of deformation that was caused by the collision with the trees.



#### SENSING AND DIAGNOSTIC MODULE

On November 8, 2006, I obtained a signed release to retrieve the data stored in the Sensing and Diagnostic Module (SDM) from the registered owner of the 2005 Chevrolet Cobalt VIN: 1G1AK52F657

On November 13, 2006, Trooper Traynor and myself returned to the St. Croix County Impound Lot. We located the SDM between the front seats of the vehicle. I photographed the SDM prior to and after its removal. The SDM appeared to be connected and undamaged.

On November 15, 2006, I used the State Patrol's Vetronix Crash Data Retrieval (CDR) equipment connected directly to the module to read the information recorded on the SDM. The data was successfully downloaded to my Panasonic CF-28 laptop computer. The data retrieved from the SDM was recorded on the CDR File Report (See attached CDR report).

#### SPEED ANALYSIS

The Vault Formula was used to determine the speed of the vehicle when it vaulted off of the driveway. The vault speed was calculated to be approximately 48 mph. A crush analysis was also performed to determine the speed lost impacting the grouping of two trees and damaging the front of the vehicle. The crush calculations indicated a speed of approximately 38 mph at the trees.

#### VEHICLE FACTORS

The ignition switch on the vehicle appears to have been in the accessory position when it impacted the trees preventing the airbags from deploying. A search of the National Highway Transportation Safety Administration (NHTSA) web site indicates five complaints of 2005 Chevrolet Cobalt ignition switches turning off while the vehicle was being driven. Three of the complaints talk about the knee or leg touching the ignition or key chain causing the engine to turn off.

On December 12, 2006, a printout of General Motors Document ID# 1869035 (inadvertent turning of key cylinder, loss of electrical system and no DTSs # 05-02-35-007A-(10/25/2006)) for the 2005 – 2007 Chevrolet Cobalt was obtained. The bulletin discusses the potential for the driver to inadvertently turn off the ignition due to low key cylinder torque/effort.

The bulletin goes on to mention that the condition is more likely to occur if the driver is short and the key chain is large and/or heavy. A shorter person would have the seat position closer to the steering column.

It appears likely that the vehicles' key turned to accessory as a result of the low key cylinder torque/effort.

While both front tires of the webicle had illegal tread depth it does not appear that this condition contributed to the crash in any way. There was an inspection of the pavement for several hundred feet leading up to the point that the webicle went onto the gravel, no tire or rim marks of any kind were found. If a vehicle has a flat tire causing loss of control, some tire marking from the flat tire and/or the metal rim should have been visible on the asphalt pavement.


#### **HUMAN FACTORS**

was traveling east down a slight grade on a straight portion of CTH N. For some unknown reason the vehicle traveled off of the pavement at a gradual angle into the south ditch. A review of Wisconsin drivers' license status showed that she had a valid instruction permit. The Instruction permit requires a qualified licensed driver be seated in the right front seat. According to the Wisconsin Department of Transportation driver license files, the right front seat passenger.

#### **ENVIRONMENTAL FACTORS**

#### Weather

The weather conditions were reported by the Weather Underground for New Richmond, Wisconsin (the nearest reporting station) on October 24, 2006, at 7:55 pm as mostly cloudy skies, visibility was 10 miles, the wind was out of the east south east at 3.5 mph and the temperature was 37.8 degrees. The weather does not appear to have been a factor in the crash.



-Page 10 of 12 -

### **Moon Position**

U.S. Naval observatory data indicates that on October 24, 2006, at 7:55 pm the moon was below the horizon and would not have been a factor in the crash.

# Roadway Condition

The roadway surface for CTH N is a traveled asphalt pavement. The surface was dry. The yellow centerlines and white edge stripes were clearly visible. The road does not appear to have been a factor in the crash.

# **Visibility Conditions**

There were no observed visibility conditions that contributed to the crash.

# INVESTIGATIVE SUMMARY

The following statements are opinions and inferences of this author. They are based upon the information reviewed to date. These statements are accurate to a reasonable degree of scientific certainty:

- None of the occupants were wearing their safety belts at the time of the crash.
- The two front seat airbags did not deploy. It appears that the ignition switch had somehow been turned from the run position to accessory prior to the collision with the trees.
- drivers' license status was a valid instruction permit.
   was violating the restrictions on her instruction permit by operating a vehicle without a qualified licensed driver in the right front seat.
- The front tires of the vehicle did not have the required minimum legal tire tread depth of 2/32 inch in two or more places on each front tire.
- The speed calculated from the vault at the driveway of 48 mph and the crush speed at the trees of 38 mph do not match the information recorded in the five seconds of pre-crash data on the SDM; this may be due to power loss.

Respectfully Submitted,

Keith A. Young

Accredited Crash Reconstruction Specialist ACTAR #1426

Wisconsin State Patrol

Wisconsin State Patrol

- Page 11 of 12 -

# **APPENDIX**

Trooper Traynor's Narrative Report
Inspector Wrights Narrative Report
Vetronix Crash Data Retrieval Report
Scaled Scene Drawing

# CRASH RECONSTRUCTION REPORT SUPPLEMENT WISCONSIN STATE PATROL NORTHWEST REGION

**CASE NUMBER: 06-49116** 

REPORTING INVESTIGATOR: Trooper William Traynor

**CRASH TYPE: Fatal** 



(715) 839-3800

#### **CRASH INFORMATION**

#### **Date of Activity**

On Tuesday, October 24 2006, I was called out from my residence to respond to a serious personal injury motor vehicle crash in the 1200 block of CTH N in St. Croix County. I responded to the scene arriving at 9:30pm. DSP Technical Reconstruction Unit (TRU) Investigator Keith Young, and DSP Troopers Lance Loonsfoot and Korey Shilts met me at the scene. St. Croix County (SCSO) Deputies Eric Johnson and Marc Sommers were also on scene. Information I received at the scene indicated a one-vehicle crash involving collision with a tree. All three occupants of the vehicle had been transported from the scene prior to my arrival. Vehicle was a white Chevrolet Cobalt displaying Wisconsin registration #605-JSN. Inspecting the scene it appeared the vehicle was eastbound on CTH N when vehicle left the roadway to the right entering a steep ditch where it continued striking a driveway embankment at 1248 CTH N. Vehicle appeared to vault after impact with the driveway continuing in an south easterly decent into the ditch where it struck a phone junction box and continuing into a tree where it impacted in the right front causing the vehicle to rotate clockwise before final rest. Vehicle sustained major frontal structure damage.

Vehicle examination showed that there were no airbag(s) deployment and a visual inspection revealed airbags still seeded inside of their steering wheel cavity and dash compartment. I was advised the occupants were not restrained inside of the vehicle. Front tires on the vehicle displayed excessive wear. Vehicle was towed to the St. Croix County Impound lot in Hudson under escort by SCSO deputy Dick Koenig.

Young and myself set up the Geodimeter 610 Total Station unit and mapped the roadway profile, tire marks, tree and final rest of the vehicle. We completed the on-scene mapping at approximately 1:00am.

On Monday, November 6, 2006 at approximately 11:00am, where I met with TRU Investigator Young. There was also a representative from the National Highway Safety Institute was inspecting the vehicle due to the non-deployment of supplement restraint system. Again using the Geodimeter 610 unit, Young and I mapped the vehicle profile of the Chevrolet Cobalt recording crush damage.

Respectfully submitted,

William Traynor Technical Crash Investigator Wisconsin State Patrol Northwest Region, Eau Claire Post



# Wisconsin Department of Transportation



State Patrol Headquarters District 3 Junction Highways 41 & 151 PO Box 984 Fond du Lac, WI 54936-0984 Telephone (920) 929-3700 Office Fax (920) 929-7666 Radio Fax (920) 929-2770

11-16-06

N501 State Highway 40 Elkmound, WI 54739

Trooper Young,

On 11-16-06, I, Inspector G. Wright, stopped at Sheboygan Chevrolet and spoke with the Service Manager, Tim Wilsing. I had him look up the recall information on VIN number 1G1AK52F657 It was informed that the recall was completed on this vehicle. I asked him if we removed the airbag/seatbelt module would have any effect on future testing, he then called and asked the technician which we were informed that this would not be a problem.

Sincerely,

Inspector G. Wright





CDR File Information

Vehicle Identification Number	1G1AK52F657	
Investigator	Keith Young	
Case Number		
Investigation Date	Wednesday, November 15 2006	
Crash Date	Tuesday, October 24 2006	
Filename	1G1AK52F657. CDR	
Saved on	Wednesday, November 15 2006 at 08:01:06 AM	=
Collected with CDR version	Crash Data Retrieval Tool 2.800	
Collecting program verification number	9238B95E	
Reported with CDR version	Crash Data Retrieval Tool 2.800	- 27.00
Reporting program verification number	9238B95E	
Interface used to collected data	Block number: 00 Interface version: 4A Date: 11-08-05 Checksum: 7500	
Event(s) recovered	Non-Deployment	

#### SDM Data Limitations

SDM Recorded Crash Events:

There are two types of SDM recorded crash events. The first is the Non-Deployment Event. A Non-Deployment Event is an event severe enough to "wake up" the sensing algorithm but not severe enough to deploy the air bag(s). It can contain Pre-Crash and Crash data. The SDM can store up to one Non-Deployment Event. This event can be overwritten by an event that has a greater SDM recorded vehicle forward velocity change. This event will be cleared by the SDM after the ignition has been cycled 250 times.

The second type of SDM recorded crash event is the Deployment Event. It also can contain Pre-Crash and Crash data. The SDM can store up to two different Deployment Events, if they occur within five seconds of one another. Deployment Events cannot be overwritten or cleared from the SDM. Once the SDM has deployed the air bag, the SDM must be replaced. The data in the Non-Deployment Event file will be locked after a Deployment Event, if the Non-Deployment Event occurred within 5 seconds before the Deployment Event unless a Deployment Level Event occurs within 5 seconds after the Deployment Event, then the Deployment Level Event will overwrite the Non-Deployment Event file.

#### SDM Data Umitations:

- -SDM Recorded Vehicle Forward Velocity Change reflects the change in forward velocity that the sensing system experienced during the recorded portion of the event. SDM Recorded Vehicle Forward Velocity Change is the change in velocity during the recording time and is not the speed the vehicle was traveling before the event, and is also not the Barrier Equivalent Velocity. This data should be examined in conjunction with other available physical evidence from the vehicle and scene when assessing occupant or vehicle forward velocity change. For Deployment Events and Deployment Level Events, the SDM will record 220 milliseconds of data after deployment criteria is met and up to 70 milliseconds before deployment criteria is met. For Non-Deployment Events, the SDM will record up to the first 300 milliseconds of data after algorithm enable. The minimum SDM Recorded Vehicle Forward Velocity Change, that is needed to record a Non-Deployment Event, is 5 MPH.

  -Maximum Recorded Vehicle Velocity Change is the maximum recorded velocity change in the vehicle's combined "X" and "Y".
- -Calculated Principal Direction of Force (PDOF) is the arctangent of the maximum observed lateral velocity change divided by the maximum observed longitudinal velocity change. PDOF is displayed where zero degrees is located at the front of the vehicle, with 90 degrees is displayed to the right side of the vehicle and so on, clockwise around the vehicle.
- -Event Recording Complete will indicate if data from the recorded event has been fully written to the SDM memory or if it has been interrupted and not fully written.
- -SDM Recorded Vehicle Speed accuracy can be affected if the vehicle has had the tire size or the final drive axis ratio changed from the factory build specifications.
- -Brake Switch Circuit Status indicates the status of the brake switch circuit.
- -Pre-Crash Electronic Data Validity Check Status indicates "Data Invalid" if the SDM receive an invalid message from the module sending the pre-crash data.
- -Driver's and Passenger's Belt Switch Circuit Status Indicates the status of the seat belt switch circuit. The Passenger Belt Switch Circuit Status for 2006 Chevrolet Cobalt Sport Coupe (AP) model vehicles, with the option package that includes
- Recaro brand seats (RPO ALV), will always report a default value of "Buckled".

  -The Time Between Non-Deployment and Deployment Events is displayed in seconds. If the time between the two events is greater than 5 seconds, "N/A" is displayed in place of the time. If the value is negative, then the Deployment Event occurred first. If the value is positive, then the Non-Deployment Event occurred first.
- -if power to the SDM is lost during a crash event, all or part of the crash record may not be recorded.
- -The ignition cycle counter relies upon the transitions through OFF->RUN->CRANK power-moding messages, on the GMLAN communication bus, to increment the counter. Applying and removing of battery power to the module will not increment the lonition counter.

1G1AK52F657

Page 1 of 9





SDM Data Source:
All SDM recorded data is measured, calculated, and stored internally, except for the following:
--Vehicle Status Data (Pre-Crash) is transmitted to the SDM, by various vehicle control modules, via the vehicle's communication network.
--The Belt Switch Circuit is wired directly to the SDM,

1G1AX52F657

Pega 2 of 9





System Status At AE

Vehicle Identification Number	**1AK52F*5*
Low Tire Pressure Warning Lamp (If Equipped)	Invalid
Vehicle Power Mode Status	Accessory
Remote Start Status (If Equipped)	Inactive
Run/Crank Ignition Switch Logic Level	Inactive
Brake System Warning Lamp (If Equipped)	OFF

System Status At 1 second

Transmission Range (If Equipped)	Fourth Gear
Transmission Selector Position (If Equipped)	Fourth Gear
Traction Control System Active (If Equipped)	Invalid
Service Engine Soon (Non-Emission Related) Lamp	OFF
Service Vehicle Scon Lamp	OFF
Outside Air Temperature (degrees F) (If Equipped)	38.3
Left Front Door Status (If Equipped)	Closed
Right Front Door Status (If Equipped)	Closed
Left Rear Door Status (If Equipped)	Unused
Right Rear Door Status (If Equipped)	Unused
Rear Door(s) Status (If Equipped)	Closed

Pre-crash data

10-diagit data		
Parameter	-2 sec	-1 sec
Reduced Engine Power Mode	OFF	OFF
Cruise Control Active (If Equipped)	No	No
Cruise Control Resume Switch Active (If Equipped)	No	No
Cruise Control Set Switch Active (If Equipped)	No	No

Pre-crash data

Parameter	-5 sec	-4 sec	-3 sec	-2 sec	-1 sec
Vehicle Speed (MPH)	71	71	71	0	0
Engine Speed (RPM)	2496	2496	2496	0	0
Percent Throttle	Invalid	Invalid	Invalid	Invalid	Invalid
Accelerator Pedal Position (percent)	Invalid	Invalid	Invalid	Invalid	Invalid
Antilock Brake System Active (If Equipped)	Invalid	invalid	Invalid	Invalid	Invalid
Lateral Acceleration (feet/s*)(If Equipped)	Invalid	Invalid	Invalid	Invalid	Invalid
Yaw Rate (degrees per second) (if Equipped)	Invalid	Invalid	Invalid	Invalid	Invalid
Steering Wheel Angle (degrees) (If Equipped)	Invalid	Invalid	Invalid	Invalid	Invalid
Vehicle Dynamics Control Active (If Equipped)	Inva!id	Invalid	Invalid	Invalid	Învalid

1G1AK52F657

Page 3 of 9






System Status At Non-Deployment Ignition Cycles At Investigation 2784 SIR Warning Lamp Status OFF SIR Warning Lamp ON/OFF Time (seconds) 655200 Number of Ignition Cycles SIR Warning Lamp was ON/OFF Continuously 2783 Ignition Cycles At Event 2784 Ignition Cycles Since DTCs Were Last Cleared 254 UNBUCKLED Driver's Belt Switch Circuit Status Diagnostic Trouble Codes at Event, fault number: N/A Diagnostic Trouble Codes at Event, fault number: N/A Diagnostic Trouble Codes at Event, fault number; N/A N/A Diagnostic Trouble Codes at Event, fault number: Diagnostic Trouble Codes at Event, fault number, N/A Diagnostic Trouble Codes at Event, fault number: N/A Maximum SDM Recorded Velocity Change (MPH) 59.84 Algorithm Enable to Maximum SDM Recorded Velocity Change (msec) 170 Driver First Stage Deployment Loop Commanded No Driver Second Stage Deployment Loop Commanded No Driver Side Deployment Loop Commanded No Oriver Pretensioner Deployment Loop Commanded
Driver (Initiator 1) Roof Rail/Head Curtain Loop Commanded No No Driver (Initiator 2) Roof Rail/Head Curtain Loop Commanded No Driver Knee Deployment Loop Commanded No Passenger First Stage Deployment Loop Commanded No Passenger Second Stage Deployment Loop Commanded No Passenger Side Deployment Loop Commanded No Passenger Pretensioner Deployment Loop Commanded No Passenger (Initiator 1) Roof Rail/Head Curtain Loop Commanded No Passenger (Initiator 2) Roof RaiVHead Curtain Loop Commanded No Passenger Knee Deployment Loop Commanded No Second Row Left Side Deployment Loop Commanded No Second Row Left Pretensioner Deployment Loop Commanded No Third Row Left Roof Rail/Head Curtain Loop Commanded Na Second Row Right Side Deployment Loop Commanded No Second Row Right Pretensioner Deployment Loop Commanded No Third Row Right Roof Rail/Head Curtain Loop Commanded No Second Row Center Pretensioner Deployment Loop Commanded No Multiple Event Counter 0 An Event(s) Preceded the Recorded Event(s) No An Event(s) was in Between the Recorded Event(s)
An Event(s) Followed the Recorded Event(s) No No The Event(s) Not Recorded was a Deployment Event(s) No The Event(s) Not Recorded was a Non-Deployment Event(s) No Crash Record Locked No Vehicle Event Data (Pre-Crash) Associated With This Event Yes Deployment Event Recorded in the Non-Deployment Record Nο **Event Recording Complete** Yes Estimated Principal Direction of Force (PDOF) degrees








Time (miliseconds)	10	20	30	40	50	80	70	80	80	100	110	120	130	140	150
Longitudinal Axis Recorded Velocity	0.00	0.00	-0.68	-1.07	-10.17	-18.98	-27.11	-34.57	-44.74	-51.52	-63.55	-64.90	-56.26	-57.62	-68.29
Time (milliseconds)	160	170	180	190	200	210	220	230	240	250	260	270	290	290	300
Longitudinal Axis Recorded Velocity	-58.97	-59.65	-60.97	-68.97	-58.97	-58.97	-58.97	-5a.97	-58.97	-68.29	0.00	0.00	0.00	0.00	0.00

1G1AK52F657

Page 5 of 9







Time (miliseconds)	10	20	30	40	50	50	70	80	80	100	110	120	130	140	150
Lateral Axis Recorded Velocity Change (MPH)	6.00	0.00	0.00	0.00	-203	-3.39	-0.10	-0.10	-174	-1.74	-474	4.74	-474	-1.74	-4.74
Time (milliseconds)	160	170	180	190	200	210	220	230	240	250	260	270	280	290	300
Lateral Axis Recorded Velocity Change (MPH)	-474	4.07	-1.07	-4.74	-1.07	-4.07	-4.74	-4.74	-1.07	-1.74	0.00	0.00	0.00	0.00	0.00

1G1AK52F657

Page 6 of 9





#### **Hexadecimal Data**

This page displays all the data retrieved from the air bag module. It contains data that is not converted by this program.

1G1AK52F657

Page 7 of 9

```
Wetronix
```



1G1AK52F857

Page 9 of 9

## WISCONSIN STATE PATROL DATA COLLECTION REPORT

	Prj/Incident: TS Operator: Survey Date:	49116 KAY 2006.1024	Time: 22.5528 Temp: 40.0 Pressure: 29.00
OS: N: E: ELE:	1 0.000 0.000 0.000	IH: 5.600 Pcode:CP1 PD: CP1	
BS: N: E: ELE:	2 51.940 0.000 2.175	SH: 0.600 Pcode:CP2 PD: CP2	HA: 0.000 VT: 93.064 DS: 52.020
PN:100	SH:0.600	Pcode:CP2	PD: CP2
	HA:0.000	VA: 93.064	SD: 52.020
PN:101	N: 51.940	E: 0.000	ELE: 2.175 CM:
	SH:0.600	Pcode:EA2	PD: EA2
	HA:78.186	VA: 94.434	SD: 204.370
PN:102	N: 41.250	E: 199.450	ELE:-11.845 CM:
	SH:0.600	Pcode: EA2	PD: EA2
	HA:75.465	VA: 95.095	SD: 155.380
PN:103	N: 38.010	E: 150.010	ELE:-8.985 CM:
	SH:0.600	Pcode:EA2	PD: EA2
	HA:70.080	VA: 96.124	SD: 98.480
PN:104	N: 33.270 SH:0.600 HA:50.114 N: 28.740	E: 92.080 Pcode:EA2 VA: 98.553 E: 34.490	ELE:-5.655 CM: PD: EA2 SD: 45.450
PN:105	SH:0.600 HA:305.352 N: 23.790	Pcode: EA2 VA: 93.192 E: -33.240	ELE:-2.050 CM: PD: EA2 SD: 40.940 ELE:2.625 CM:
PN:106	SH:0.600	Pcode: EA2	PD: EA2
	HA:281.283	VA: 89.096	SD: 96.130
	N: 19.120	E: -94.200	ELE: 6.400 CM:
PN:107	SH:0.600	Pcode:EA2	PD: EA2
	HA:275.183	VA: 88.094	SD: 155.640
	N: 14.390	E: -154.900	ELE:10.000 CM:
PN:108	SH:0.600	Pcode: EA2	PD: EA2
	HA:272.234	VA: 87.431	SD: 221.130
	N: 9.230	E: -220.760	ELE:13.800 CM:
PN:109	SH:0.600	Pcode: EA2	PD: EA2
	HA:270.352	VA: 87.315	SD: 304.140
	N: 3.120	E: -303.840	ELE:18.105 CM:
PN:110	SH:0.600 HA:269.211 N: -4.580	Pcode:EA2 VA: 87.252	PD: EA2 SD: 404.970
PN:111	SH:0.600 HA:268.441	Pcode: EA2 VA: 87.263	ELE:23.220 CM: PD: EA2 SD: 490.480
PN:112	N: -10.810	E: -489.870	ELE:26.900 CM:
	SH:0.600	Pcode:EA1	PD: EA1
	HA:265.512	VA: 87.264	SD: 485.880

		_		0 <i>c cc</i> 0	<b>-11</b> .
	N: -35.070		-484.120	ELE:26.660	CM:
PN:113	SH: 0.600	Pcode:		PD: EA1	
	HA: 265.525		87.256	SD: 416.060	
	พ: -29.860		-414.570	ELE:23.645	CM:
PN:114	SH:0.600	Pcode:		PD: EA1	
	HA:265.571	VA:	87.291	SD: 334.180	
	N: -23.560	E:	-333.020	ELE:19.655	CM:
PN:115	SH:0.600	Pcode:	EA1	PD: EA1	
	HA: 266.055	VA:	87.404	SD: 235.180	
	N: -15.990	E:	-234.440	ELE:14.535	CM:
PN:116	SH: 0.600	Pcode:	EA1	PD: EA1	
	HA: 266.200		88.092	SD: 152.890	
	N: -9.770		-152.500	ELE:9.920	CM:
PN:117	SH: 0.600	Pcode:		PD: EA1	0
	HA: 266.404		90.012	SD: 70.300	
	N: -4.080		-70.180	ELE:4.975	CM:
PN:118	SH: 0.600	Pcode:		PD: EA1	CP1.
PN:110	HA: 82.134				
			104.103 25.230	SD: 26.260	ov.
DVI - 3 4 0	N: 3.440			ELE:-1.430	CM:
PN:119	SH: 0.600	Pcode:		PD: EA1	
	HA: 85.105		94.473	SD: 202.170	
	N: 16.930		200.760	ELE:-11.885	CM:
PN:120	SH:0.600	Pcode:		PD: PAVM1	
	HA:81.432		94.405	SD: 204.620	
	N: 29.360	E:	201.810	ELE:-11.695	CM:
PN:121	SH:0.600	Pcode:	PAVM1	PD: PAVM1	•
	HA:80.450	VA:	94.595	SD: 164.480	
	N: 26.340	E:	161.720	ELE:-9.330	CM:
PN:122	SH:0.600	Pcode:	PAVM1	PD: PAVM1	
	HA:77.054	VA:	96.165	SD: 94.380	
	N: 20.960	E:	91.450	ELE:-5.325	CM:
PN:123	SH: 0.600	Pcode:		PD: PAVM1	
	HA:52.046		102.526	SD: 25.860	
	N: 15.490		19.890	ELE:-0.765	CM:
PN:124	SH:0.600	Pcode:		PD: PAVM1	
	HA:279.571		90.373	SD: 56.650	
	N: 9.790		-55.800	ELE:4.385	CM:
PN:125	SH:0.600	Pcode:		PD: PAVM1	C11+
FM. IZJ	HA:271.572		88.214	SD: 127.010	
	N: 4.340			ELE:8.635	C11 -
DVI-126			-126.890		CM:
PN:126	SH:0.600	Pcode:		PD: PAVMI	
	HA:269.251		87.403	SD: 212.490	
	N: -2.150		-212.300	ELE:13.625	CM:
PN:127	SH:0.600	Pcode:		PD: PAVM1	
	HA:268.096		87.273	SD: 315.950	
	N: -10.100		-315.470	ELE:19.005	CM:
PN:128	SH:0.600	Pcode:		PD: PAVMI	
	HA:267.380		87.232	SD: 401.460	
	N: -16.560	E:	-400.700	ELE:23.290	CM:
PN:129	SH:0.600	Pcode:	PAVM1	PD: PAVM1	
	HA:267.211	VA:	87.231	SD: 465.770	
	N: -21.490	E:	-464.790	ELE:26.235	CM:
PN:130	SH:0.600	Pcode:		PD: ECA1	
	HA:265.152		87.276	SD: 466.680	
	N: -38.560		-464.630	ELE:25.635	CM:
PN:131	SH:0.600	Pcode:		PD: ECA1	
	HA:265.113		87.283	SD: 400.910	
		7520	y,	JJ. 400+J10	

```
N: -2.930
                       E:
                              121.160
                                          ELE:-9.815
                                                          CM:
                       Pcode: VEH1
        SH:5.800
                                          PD: VEH1
PN:151
        HA:92.382
                       VA:
                              94.464
                                          SD: 122.430
        พ: -5.620
                       E:
                              121.880
                                          ELE:-10.395
                                                          CM:
                       Pcode: VEH1
                                           PD: VEH1
PN:152
        SH:5.800
                       VA:
                              95:242
                                          SD: 121.850
        HA:96.471
                              120.460
                                          ELE:-11.675
                                                          CM: AXLE
        N: -14.330
                       E:
                       Pcode: VEH1
                                          PD: VEH1
PN:153
        SH:5.800
                       VA:
                              95.362
                                           SD: 121.090
        HA:97.170
        N: -15.280
                       E:
                              119.540
                                          ELE:-12.025
                                                          CM:
                       Pcode: VEH1
                                          PD: VEH1
PN:154
        SH:5.800
        HA:97.293
                       VA:
                              95.412
                                          SD: 119.200
        N: -15.460
                       E:
                              117.600
                                          ELE:-12.015
                                                          CM:
        SH:5.800
                       Pcode: VEH1
                                           PD: VEH1
PN:155
                       VA:
                              95.345
                                          SD: 117.860
        HA:96.521
                              116.460
                                          ELE:-11.665
        N: -14.030
                       E:
                                                          CM:
PN:156
        SH:5.800
                       Pcode: VEH1
                                           PD: VEH1
                                          SD: 116.820
        HA:96.251
                       VA:
                              95.364
        N: -13.000
                       E:
                              115.530
                                          ELE:-11.620
                                                          CM:
PN:157
        SH:5.800
                       Pcode: VEH1
                                           PD: VEH1
                                           SD: 116.520
        HA:95.321
                       VA:
                              95.243
                              115.460
                                           ELE:-11.180
                                                          CM: AXLE
        N: -11.190
                       Pcode: VEH1
PN:150
        SH:5.800
                                          PD: VEH1
        HA:92.343
                       VA:
                              94.463
                                          SD: 116.530
        N: -5.220
                              116.010
                                          ELE:-9.900
                       E:
                                                          CM:
PN:159
        SH:5.800
                       Pcode:XYZ2
                                           PD: XYZ2
                              86.301
                                           SD: 271.070
        HA:266.000
                       VA:
                              -269.900
        N: -18.870
                       E:
                                          ELE:16.340
                                                          CM:
PN:160
        SH:5.800
                       Pcode:TM1
                                           PD: TM1
        HA:264.182
                       VA:
                              86,281
                                           SD: 186.960
        N: -18.520
                       E:
                              -185.680
                                          ELE:11.310
                                                          CM:
                       Pcode:TM1
        SH:5.800
                                           PD: TM1
PN:161
                       VA:
                              86.300
                                           SD: 170.260
        HA:264.075
                       E:
                              -169.050
                                          ELE:10.190
        N: -17.380
                                                          CM:
                       Pcode:TM1
PN:162
        SH:5.800
                                           PD: TM1
                             86.302
                                          SD: 153.030
        HA:263.531
                       VA:
        N: -16.270
                       E:
                              -151.880
                                          ELE: 9.130
                                                          CM:
                                           PD: TM1
                       Pcode:TM1
PN:163
        SH:5.800
        HA:262.565
                              86.375
                                          SD: 128.010
                       VA:
        N: -15.690
                              -126.830
                                          ELE: 7.325
                       E:
                                                          CM:
PN:164
        SH:5.800
                       Pcode:TM1
                                           PD: TMl
                       VA:
                              86.576
                                           SD: 94.990
        HA:260.491
        พ: -15.130
                       E:
                              -93.640
                                          ELE:4.830
                                                          CM:
        SH: 5.800
PN:165
                       Pcode:TM1
                                          PD: TM1
                              87.001
                                          SD: 79.190
        HA: 258.521
                       VA:
                              -77.600
        N: -15.270
                       E:
                                          ELE:3.940
                                                          CM:
PN:166
        SH:5.800
                       Pcode:TM1
                                          PD: TM1
                       VA:
                              86.333
                                          SD: 75.890
        HA: 258.342
        N: -15.010
                       E:
                              ~74.250
                                          ELE:4.355
                                                          CM:
PN:167
        SH: 5.800
                       Pcode:TM2
                                          PD: TM2
                                          SD: 19.150
        HA: 229.505
                       VA:
                              92.361
        N: -12.330
                       E:
                              -14.620
                                          ELE:-1.070
                                                          CM:
PN:168
        SH:5.800
                       Pcode:TM2
                                          PD: TM2
        HA:122.282
                       VA:
                              99.254
                                          SD: 23.980
        N: -12.700
                       E:
                              19.950
                                          ELE:-4.130
                                                          CM:
PN:169
        SH:5.800
                       Pcode: TM2
                                          PD: TM2
        HA: 107.046
                       VA:
                              97.304
                                          SD: 52.640
```

	ท: -15.330	E:	49.890	ELE:-7.080	CM:
PN: 170	SH:5.800	Pcode	:TM2	PD: TM2	
	HA:104.533	VA:	97.144	SD: 67.930	
	พ: -17.320	E:	65.130	ELE:-8.765	CM:
PN:171	SH:5.800	Pcode	:TM3	PD: TM3	
	HA:172.540	VA:	101.024	SD: 16.330	
	พ: -15.900	E:	1.980	ELE:-3.330	CM:
PN:172	SH:5.800	Pcode	:TM3	PD: TM3	
	HA:125.215	VA:	100.104	SD: 31.620	
	N: -18.010	E:	25.380	ELE:-5.785	CM:
PN:173	SH:5.800	Pcode	:TM3	PD: TM3	
	HA:112.383	VA:	98.380	SD: 49.740	
	N: -18.930	E:	45.390	ELE:-7.670	CM:
PN: 174	SH:5.800	Pcode	:TM3	PD: TM3	
	HA:109.162	VA:	97.395	SD: 64.600	
	N: -21.130	E:	60.430	ELE:-8.815	CM:
PN:175	SH:5.800	Pcode	:XYZ1	PD: XYZ1	
	HA:106.446	VA:	97.340	SD: 71.100	
	N: -20.310	E:	67.490	ELE:-9.565	CM:
PN:176	SH:5.800	Pcode	:DTRE1	PD: DTRE1	
	HA:102.305	VA:	95.455	SD: 118.110	
	N: -25.460	E:	114.720	ELE:-12.065	CM:
PN: 177	SH:0.600	Pcode	:CP2	PD: BACKSITE	
	HA:0.000	VA:	93.061	SD: 52.010	
	N: 51.930	E:	0.000	ELE:2.185	CM:

#### WISCONSIN STATE PATROL DATA COLLECTION REPORT

	Prj/Incident: TS Operator: Survey Date:	WDT		1.3607 8.0 9.00
	_			
os: N:	1 0.000	IH: 4.950 Pcode:CP1		
E:	0.000	PD: OS		
BS:	2	SH: 5.600	на: 0.004	
	86.060	Pcode: CP2	VT: 88.405 DS: 86.080	
	0.020 1.330	PD: BS	D2: 00.000	
PN:201	SH:5.600	Pcode:VEH2	PD: PROFILE	
111.201	HA:348.426	VA: 84.222	SD: 19.420	
	พ: 18.960	E: -3.780	ELE:1.255	CM: RFT
PN:202	SH:5.600	Pcode: VEH2	PD: PROFILE	
	HA:349.184	VA: 84.401	SD: 19.860	m.
PN:203	N: 19.430 SH:5.600	E: -3.670 Pcode:VEH2	ELE:1.195 PD: PROFILE	CM:
EN.203	HA:348.526	VA: 87.546	SD: 22.310	
	N: 21.880	E: -4.300	ELE: 0.160	CM:
PN:204	SH:5.600	Pcode: VEH2	PD: PROFILE	
	HA:348.493	VA: 88.082	SD: 25.980	
	N: 25.480	E: -5.030	ELE:0.195	CM: RRT
PN:205	SH:5.600	Pcode: VEH2	PD: PROFILE	
	HA:349.212 N: 26.890	VA: 88.076 E: +5.050	SD: 27.370 ELE:0.240	CM:
PN:206	SH:5.600	Pcode: VEH2	PD: PROFILE	
1111200	HA:349.335	VA: 88.081	SD: 28.120	
	N: 27.640	E: -5.090	ELE:0.265	CM:
PN:207	SH:5.600	Pcode: VEH2	PD: PROFILE	
	HA:349.554	VA: 88.081	SD: 28.550	
DIV. 000	N: 28.100	E: -4.990	ELE:0.280	CM:
PN:208	SH:5.600 HA:350.291	Pcode: VEH2 VA: 88.085	PD: PROFILE	
	N: 28.410	VA: 88.085 E: -4.760	SD: 28.820 ELE:0.280	CM:
PN:209	SH:5.600	Pcode: VEH2	PD: PROFILE	
	HA:351.371	VA: 88-071	SD: 29.050	
	N: 28.720	E: -4.230	ELE:0.305	CM:
PN:210	SH:5.600	Pcode: VEH2	PD: PROFILE	
	HA:353.136	VA: 88.042	SD: 29.240	
	N: 29.020	E: -3.440	ELE:0.335	CM:
PN:211	SH:5.600	Pcode: VEH2	PD: PROFILE	
	HA:354.294 N: 29.150	VA: 88.025 E: ~2.810	SD: 29.300 ELE:0.350	CM.
PN:212	SH:5.600	Pcode: VEH2	PD: PROFILE	CM:
	HA:355.461	VA: 88.032	SD: 29.350	
	N: 29.250	E: -2.160	ELE:0.345	CM:
PN:213	SH:5.600	Pcode: VEH2	PD: PROFILE	<del></del>
	HA:357.273	VA: 88.031	SD: 29.310	

```
ELE: 0.345
                                                           CM:
        N: 29.270
                        E:
                               -1.300
                                            PD: PROFILE
PN:214
                        Pcode: VEH2
        SH:5.600
                                            SD: 29.220
                        VA:
                              88.085
        HA:358.194
                        E:
                               -O.850
                                            ELE: 0.295
                                                           CM:
        N: 29.190
                                            PD: PROFILE
PN:215
        SH:5.600
                        Pcode: VEH2
                                            SD: 29.050
                        VA:
                               88.084
        HA:359.000
                        E:
                               -0.510
                                            ELE: 0.290
                                                           CM:
        N: 29.030
                        Pcode: VEH2
                                            PD: PROFILE
PN:216
        SH:5.600
                                            SD: 28.570
                        VA:
                              88.093
        HA:359.424
                               -0.140
                                            ELE:0.270
                                                           CM:
                        E:
        N: 28.560
PN:217
                        Pcode: VEH2
                                            PD: PROFILE
        SH:5.600
                                            SD: 27.780
        HA:0.182
                        VA:
                              B8.115
                        E:
                                            ELE: 0.225
                                                           CM:
        N: 27.770
                               0.150
PN:218
                                            PD: PROFILE
        SH:5.600
                        Pcode: VEH2
        HA:1.165
                        VA:
                               88.102
                                            SD: 26.540
        N: 26.520
                        E:
                               0.590
                                            ELE:0.195
                                                           CM: LRT
PN:219
                        Pcode: VEH2
                                            PD: PROFILE
        SH:5.600
                                            SD: 22.970
        HA:3.211
                        VA:
                              87.582
                        E:
                                            ELE:0.160
                                                           CM:
        N: 22.920
                              1.340
PN:220
                        Pcode: VEH2
                                            PD: PROFILE
        SH:5.600
        HA: 6.055
                        VA:
                               87.502
                                            SD: 19.200
        N: 19.080
                        E:
                              2.040
                                            ELE:0.075
                                                           CM:
                                            PD: PROFILE
PN:221
        SH:5.600
                        Pcode: VEH2
        HA:5.323
                        VA:
                              87.481
                                            SD: 17.850
                              1.720
        พ: 17.750
                        E:
                                                           CM:
                                            ELE:0.035
PN:222
        SH:5.600
                        Pcode: VEH2
                                            PD: PROFILE
                        VA:
                                            SD: 17.860
        HA:5.334
                               87.481
        N: 17.760
                        E:
                               1.730
                                            ELE: 0.035
                                                           CM: LFT
PN:223
        SH:5.600
                        Pcode: VEH2
                                            PD: PROFILE
                        VA:
        HA:3.183
                              87.283
                                            SD: 16.390
                        E:
        N: 16.340
                               0.940
                                            ELE:0.070
                                                           CM:
PN:224
        SH:0.000
                        Pcode: VEH2
                                            PD: PROFILE
        HA:1.585
                        VA:
                               99.413
                                            SD: 16.360
                        E:
        พ: 16.120
                               0.560
                                            ELE:2.195
                                                           CM:
PN:225
                        Pcode: VEH2
        SH:0.000
                                            PD: PROFILE
                        VA:
         HA:358.115
                               102.441
                                            SD: 16.330
        N: 15.920
                        E:
                               -0.500
                                            ELE:1.350
                                                           CM:
PN:226
        SH:0.000
                        Pcode: VEH2
                                            PD: PROFILE
        HA:357.030
                        VA:
                               102.254
                                            SD: 16.180
        N: 15.780
                        E:
                               -0.810
                                            ELE: 1.465
                                                           CM:
PN:227
        SH:0.000
                        Pcode: VEH2
                                            PD: PROFILE
                        VA:
        HA:355.492
                               102.481
                                            SD: 16.490
                        E:
        N: 16.040
                               -1.170
                                            ELE: 1.295
                                                           CM:
PN:228
        SH:0.000
                        Pcode: VEH2
                                            PD: PROFILE
         HA:355.073
                        VA:
                               99.532
                                            SD: 17.860
        N: 17.530
                        E:
                               -1.500
                                            ELE:1.880
                                                           CM:
PN:229
        SH:0.000
                        Pcode: VEH2
                                            PD: PROFILE
        HA:354.355
                        VA:
                               99.532
                                            SD: 18.480
        N: 18.130
                        E:
                               -1.710
                                            ELE: 1.775
                                                           CM:
PN:230
        SH:0.000
                        Pcode: VEH2
                                            PD: PROFILE
        HA:354.005
                        VA:
                               99.180
                                            SD: 18.360
        พ: 18.020
                               -1.890
                        E:
                                            ELE:1.985
                                                           CM:
PN:231
        SH:0.000
                        Pcode: VEH2
                                            PD: PROFILE
        HA:352.561
                        VA:
                              99.243
                                            SD: 18.330
        N: 17.950
                        E:
                               -2.220
                                            ELE: 1.955
                                                           CM:
PN:232
                        Pcode: VEH2
        SH:0.000
                                            PD: PROFILE
        HA:352.156
                        VA:
                              99.435
                                            SD: 18.010
```

	N: 17.590	E:	-2.390	ELE:1.905	CM:
PN:233	SH:0.000	Pcode	:VEH2	PD: PROFILE	
	HA:351.042	VA:	99.425	SD: 17.910	
	N: 17.440	E:	-2.740	ELE:1.925	CM:
PN:234	SH:0.000	Pcode	:VEH2	PD: PROFILE	
	HA:350.021	VA:	98.125	SD: 18.480	
	N: 18.020	E:	-3.170	ELE:2.310	CM:
PN:235	SR:0.000	Pcode	:VEH2	PD: PROFILE	
	HA:349.154	VA:	98.172	SD: 18.520	
	N: 18.010	E:	-3.420	ELE:2.280	CM:
PN:236	SH:0.000	Pcode	:VEH2	PD: PROFILE	
23,1004	HA:348.285	VA:	98.040	SD: 18.470	
	N: 17.920	E:	-3.650	ELE:2.355	CM:
PN:237	SH:0.000		:VEH2	PD: PROFILE	
	HA:348.254	VA:	98.040	SD: 18.470	
	N: 17.910	E:	-3.670	ELE:2.360	CM:
PN:238	SH:0.000	Pcode	:VEH2	PD: PROFILE	
	HA:347.055	VA:	98.325	SD: 18.030	
	N: 17.380	E:	-3.980	ELE:2.270	CM:
PN:239			:VEH2	PD: PROFILE	
	HA:346.211	VA:	98.175	SD: 18.060	
	พ: 17.360	E:	~4.220	ELE:2.345	CM:
PN: 240	SH: 5.600	Pcode	:VEH2	PD: PROFILE	
	HA:345.185	VA:	87.384	SD: 18.910	
	N: 18.270	E:	-4.790	ELE:0.125	CM:
PN:241	SH:5.600	Pcode	:VEH2	PD: PROFILE	
	HA:348.441	VA:	83.595	SD: 19.410	
	N: 18.930	E:	-3.770	ELE:1.380	CM:
				:	

































