

# NHTSA Investigations into Sudden Unintended Acceleration, 1999-Present

NHTSA ACTION NUMBER	MAKE	MODEL	YEAR	DATE OPENED	SUBJECT
DP03003	LEXUS	GS400, LS400	1997-2000	20030717	UNCONTROLLED ACCELERATION
DP05002	LEXUS, TOYOTA	ES, CAMRY	2002-2005	20050805	VEHICLE SPEED CONTROL DEFECT PETITION
DP06002	JEEP	COMMANDER	2006	20060713	
DP06003	TOYOTA	CAMRY	2002-2006	20060914	ENGINE SURGING
DP08001	TOYOTA	TACOMA	2006-2007	20080131	SUDDEN AND UNCONTROLLED ACCELERATION
DP09001	LEXUS	ES300, ES350	2002-2003, 2007	20090408	UNWANTED AND UNINTENDED ACCELERATION
EA02015	CADILLAC, CHEVROLET, GMC	ESCALADE, AVALANCHE, SILVERADO, SUBURBAN, TAHOE, YUKON, YUKON XL	1999-2002	20020801	THROTTLE STICKING
EA05014	FORD	MUSTANG	2003-2004	20050913	ACCELERATOR PEDAL INTERFERENCE
EA07010	TOYOTA, LEXUS	CAMRY, ES	2007-2008	20070808	UNWANTED ACCELERATION, FLOOR MAT
EA08014	TOYOTA	SIENNA	2004	20080808	ACCELERATOR PEDAL INTERFERENCE
EA99001	FORD	EXPLORER	1997-1998	19990107	THROTTLE STICKING
PE00048	DODGE	RAM 2500, RAM 3500	1994-1996	20001211	LOSS OF THROTTLE CONTROL
PE04021	LEXUS	ES300, CAMRY	2002-2003	20040303	THROTTLE CONTROL SYSTEM
PE04023	AUDI	A6	1998-1999	20040305	STUCK-OPEN THROTTLE
PE04023	AUDI	A6	1998	20040305	STUCK-OPEN THROTTLE
PE05037	FORD, MERCURY	EXPLORER, MOUNTAINEER	2002	20050707	STUCK ENGINE THROTTLE
PE05038	FORD	MUSTANG	2003-2004	20050707	ACCELERATOR PEDAL INTERFERENCE
PE07016	LEXUS	ES350	2007	20070329	ACCESSORY FLOOR MAT
PE08025	TOYOTA	SIENNA	2004	20080410	UNWANTED ACCELERATION
PE08039	WEATHERTECH	W39 (FLOOR MATS)	9999	20080625	ACCELERATOR PEDAL-FLOOR MAT INTERFERENCE

Source: <http://www.VSIRC.com>