Year	Make	Model		Toyota SSC 70F AWFM Pedal Iterference (NHTSA Recall 07E082)	Lexus SSC 7LB AWFM Pedal Iterference (NHTSA Recall 07E082)	Toyota SSC 90B (NHTSA Recall 09V023 - Floor Carpet Cover)	(NHTSA Recalls	Lexus SSC 9LG (NHTSA Recalls 09V388 and 10V023 - Floor Mat, Pedal Modification and Brake-to-Idle upgrade)	Toyota SSC A0A - Sticking CTS Accelerator Pedal (NHTSA Recall 10V017)	Lexus SSC BLB Plastic Pad Embedded Into Floor Carpet (NHTSA Recall 11V115)	Lexus SSC BLC (Interim B2C) Driver's Side Floor Carpet Cover & Retention Clip (NHTSA Recall 11V112)	Toyota B0A (Interim B1A) Driver's Side Floor Carpet Cover and Retention Clips (NHTSA Recall 11V112)
2003	Toyota	4Runner	N/A	N/A	N/A	N/A	YES PHASE 10 (Dealer Letter 2/24/2011; Owner Letter Start Late April 2011) (Does not include Brake-to-Idle	N/A	N/A	N/A	N/A	N/A
2004	Lexus	RX330	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Dealer Letter Sent 2/24/2011. Dealer letter and Technical information with Remedy sent 4/27/2011	N/A
2004	Toyota	4Runner	N/A	N/A	N/A	N/A	YES PHASE 10 (Dealer Letter 2/24/2011; Owner Letter Start Late April 2011) (Does not include Brake-to-Idle	N/A	N/A	N/A	N/A	N/A
2004	Toyota	Highlander	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Dealer Letter Sent 2/24/2011 (Certain 2004 Models) Dealer letter and Technical information with Remedy sent 4/28/2011
2004	Toyota	Prius	N/A	N/A	N/A	N/A	YES - PHASE 5 (Dealer letter 4/12/2010; Owner Letter Start 4/23/2010) Hybrid vehicles do not get Brake-to-Idle feature. Different system designed into Hybrids.)		N/A	N/A	N/A	N/A
2004	Toyota	Sienna	N/A	N/A	N/A	YES (Vehices built between 1/10/03 and 6/11/03)		N/A	N/A	N/A	N/A	N/A
2005	Lexus	RX330	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Dealer Letter Sent 2/24/2011. Dealer letter and Technical information with Remedy sent 4/27/2011	N/A

Year	Make		(NHTSA Recall	Toyota SSC 70F AWFM Pedal Iterference (NHTSA Recall 07E082)	Lexus SSC 7LB AWFM Pedal Iterference (NHTSA Recall 07E082)	Toyota SSC 90B (NHTSA Recall 09V023 - Floor Carpet Cover)	(NHTSA Recalls 09V388 and 10V023 -	10V023 - Floor Mat, Pedal Modification and	Toyota SSC A0A - Sticking CTS Accelerator Pedal (NHTSA Recall 10V017)	Lexus SSC BLB Plastic Pad Embedded Into Floor Carpet (NHTSA Recall 11V115)	Lexus SSC BLC (Interim B2C) Driver's Side Floor Carpet Cover & Retention Clip (NHTSA Recall 11V112)	Toyota B0A (Interim B1A) Driver's Side Floor Carpet Cover and Retention Clips (NHTSA Recall 11V112)
2005	Lexus	RX400h	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Dealer Letter Sent 2/24/2011. Dealer letter and Technical information with Remedy sent 4/27/2011	N/A
2005	Toyota	Avalon	N/A	N/A	N/A	N/A	YES - PHASE 3 (Dealer Letter 2/23/2010; Owner Letter Start 3/1/2010)		YES 2/2/2010 (Customer can reques new pedal. Dealers are not to offer new pedal)	N/A	N/A	N/A
2005	Toyota	Highlander	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Dealer Letter Sent 2/24/2011 (Certain 2005 Models) Dealer letter and Technical information with Remedy sent 4/28/2011
2006	Toyota	Highlander HV	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Dealer Letter Sent 2/24/2011 (Certain 2006 Models) Dealer letter and Technical information with Remedy sent 4/28/2011
2005	Toyota	Prius	N/A	N/A	N/A	N/A	YES - PHASE 5 (Dealer letter 4/12/2010; Owner Letter Start 4/23/2010) Hybrid vehicles do not get Brake-to-Idle feature. Different system designed into Hybrids.)		N/A	N/A	N/A	N/A
2005	·			N/A	N/A	N/A	YES PHASE 9 (Dealer Letter 7/16/2010; Owner Letter Start Late July 2010) (Does not include Brake-to-Idle		N/A	N/A	N/A	N/A
				N/A N/A	N/A N/A	N/A N/A			N/A N/A	Letter to Dealer 2/24/2011 Letter to Dealer 2/24/2011	N/A N/A	N/A N/A

Year	Make	Model	•	Toyota SSC 70F AWFM Pedal Iterference (NHTSA Recall 07E082)		Toyota SSC 90B (NHTSA Recall 09V023 - Floor Carpet Cover)	Toyota SSC 90L & 91L (NHTSA Recalls 09V388 and 10V023 - Floor Mat, Pedal Modification and Brake to-Idle upgrade)	10V023 - Floor Mat, Pedal Modification and	Toyota SSC A0A - Sticking CTS Accelerator Pedal (NHTSA Recall 10V017)	Lexus SSC BLB Plastic Pad Embedded Into Floor Carpet (NHTSA Recall 11V115)	Lexus SSC BLC (Interim B2C) Driver's Side Floor Carpet Cover & Retention Clip (NHTSA Recall 11V112)	Toyota B0A (Interim B1A) Driver's Side Floor Carpet Cover and Retention Clips (NHTSA Recall 11V112)
2006	Lexus	IS 250	Dealer Letter 12/20/2005	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
2006	Lexus	IS 350	N/A	N/A	N/A	N/A	N/A	YES - PHASE 2 (Dealer letter 4/5/2010; Owner Letter Start 4/23/2010)	N/A	N/A	N/A	N/A
2006	Lexus	IS F	N/A	N/A	N/A	N/A	N/A	YES - PHASE 2 (Dealer letter 4/5/2010; Owner Letter Start 4/23/2010)	N/A	N/A	N/A	N/A
2006	Lexus	IS C	N/A	N/A	N/A	N/A	N/A		N/A	N/A	N/A	N/A
2006	Lexus	RX330	N/A	N/A	N/A	N/A	N/A		N/A	N/A	Dealer Letter Sent 2/24/2011. Dealer letter and Technical information with Remedy sent 4/27/2011	N/A
2006	Lexus	RX400h	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Dealer Letter Sent 2/24/2011. Dealer letter and Technical information with Remedy sent 4/27/2011	N/A
2006	Toyota	Highlander	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Dealer Letter Sent 2/24/2011 (Certain 2006 Models) Dealer letter and Technical information with Remedy sent 4/28/2011
2006	Toyota	Highlander HV	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Dealer Letter Sent 2/24/2011 (Certain 2007 Models) Dealer letter and Technical information with Remedy sent 4/28/2011

Year	Make	Model	Lexus SSC 5LC (NHTSA Recall 05V565 - Accelerator Pedal Recall)	Toyota SSC 70F AWFM Pedal Iterference (NHTSA Recall 07E082)	Iterference (NHTSA	Toyota SSC 90B (NHTSA Recall 09V023 - Floor Carpet Cover)	(NHTSA Recalls 09V388 and 10V023 - Floor Mat, Pedal	10V023 - Floor Mat, Pedal Modification and	Sticking CTS Accelerator Pedal (NHTSA Recall 10V017)	Lexus SSC BLB Plastic Pad Embedded Into Floor Carpet (NHTSA Recall 11V115)	Lexus SSC BLC (Interim B2C) Driver's Side Floor Carpet Cover & Retention Clip (NHTSA Recall 11V112)	Toyota B0A (Interim B1A) Driver's Side Floor Carpet Cover and Retention Clips (NHTSA Recall 11V112)
2006	Toyota	RAV4	N/A	N/A	N/A	N/A	YES PHASE 11 (Dealer Letter TBD; Owner Letter Start TBD) (Does not include Brake-to- Idle Upgrade)	N/A	N/A	N/A	N/A	N/A
2006	Toyota	Tacoma	N/A	N/A	N/A	N/A	YES PHASE 9 (Dealer Letter 7/16/2010; Owner Letter Start Late July 2010) (Does not include Brake-to-Idle	N/A	N/A	N/A	N/A	N/A
2007	Lexus	ES350	N/A	N/A	Recall inititiated 9/28/2007 (Certain Vehicles)	N/A	N/A	YES - PHASE 1 (Dealer letter 12/21/2009; Owner Letter Start 12/31/2009)	N/A	N/A	N/A	N/A
2007	Lexus	GS300 AWD	N/A	N/A	N/A	N/A	N/A		N/A	Letter to Dealer 2/24/2011 (Models mfg. throguh early July 2006	N/A	N/A
2007	Lexus	GS350 AWD	N/A	N/A	N/A	N/A	N/A	N/A	N/A	Letter to Dealer 2/24/2011 (Vehicles Mfg. Mid July - Mid Aug. 2006)	N/A	N/A
2007	Lexus	IS 250	N/A	N/A	N/A	N/A	N/A	YES - PHASE 2 (Dealer letter 4/5/2010; Owner Letter Start 4/23/2010)	N/A	N/A	N/A	N/A
2007	Lexus	IS 350	N/A	N/A	N/A	N/A	N/A	YES - PHASE 2 (Dealer letter 4/5/2010; Owner Letter Start 4/23/2010)	N/A	N/A	N/A	N/A
2007	Lexus	IS F	N/A	N/A	N/A	N/A	N/A	,	N/A	N/A	N/A	N/A
2007	Lexus	IS C	N/A	N/A	N/A	N/A	N/A	,	N/A	N/A	N/A	N/A
2007	Lexus	RX350	N/A	N/A	N/A	N/A	N/A		N/A	N/A	Dealer Letter Sent 2/24/2011. Dealer letter and Technical information with Remedy sent 4/27/2011	N/A

## Toyota Recall Matrix

Year	Make	Model	Lexus SSC 5LC (NHTSA Recall 05V565 - Accelerator Pedal Recall)		AWFM Pedal Iterference (NHTSA	Toyota SSC 90B (NHTSA Recall 09V023 - Floor Carpet Cover)	(NHTSA Recalls 09V388 and 10V023 - Floor Mat, Pedal	10V023 - Floor Mat, Pedal Modification and	Sticking CTS Accelerator Pedal (NHTSA Recall 10V017)	Lexus SSC BLB Plastic Pad Embedded Into Floor Carpet (NHTSA Recall 11V115)	Lexus SSC BLC (Interim B2C) Driver's Side Floor Carpet Cover & Retention Clip (NHTSA Recall 11V112)	Toyota B0A (Interim B1A) Driver's Side Floor Carpet Cover and Retention Clips (NHTSA Recall 11V112)
2007	Toyota	4Runner	N/A	N/A	N/A	N/A	YES PHASE 10 (Dealer Letter 2/24/2011; Owner Letter Start Late April 2011) (Does not include Brake-to-Idle	N/A	N/A	N/A	N/A	N/A
2007	Toyota	Avalon	N/A	N/A	N/A	N/A	YES - PHASE 3 (Dealer Letter 2/23/2010; Owner Letter Start 3/1/2010)		YES 2/2/2010 (Customer can request new pedal. Dealers are not to offer new pedal)	N/A	N/A	N/A
2007	Toyota	Camry w/CTS Pedals	N/A	Recall inititiated 9/28/2007 (Certain Vehicles)	N/A	N/A	YES - PHASE 2 CTS Pedals (Dealer Letter 2/4/2010; Owner Letter Start 2/16/2010)		YES 2/2/2010 (Customer can request new pedal. Dealers are not to offer new pedal)	N/A	N/A	N/A
2007	Toyota	Camry w/Denso Pedals	N/A	Recall inititiated 9/28/2007 (Certain Vehicles)	N/A	N/A	YES - PHASE 1 DENSO Pedals (Dealer letter 2/2/2010; Owner Letter Start 2/16/2010)	N/A	N/A	N/A	N/A	N/A
2007	Toyota	Camry HV	N/A	Recall inititiated 9/28/2007 (Certain Vehicles)	N/A	N/A	YES - PHASE 1 (Dealer letter 2/2/2010; Owner Letter Start 2/16/2010) Hybrid vehicles do not get Brake-to-Idle feature. Different system designed into Hybrids.)		YES 2/2/2010 (22 Specific Hybrid Vehicles built with CTS pedal and need to be fixed. Other Hybrids built with differenent Pedal)	N/A	N/A	N/A
2007	Toyota	Prius	N/A	N/A	N/A	N/A	YES - PHASE 5 (Dealer letter 4/12/2010; Owner Letter Start 4/23/2010) Hybrid vehicles do not get Brake-to-Idle feature. Different system designed into Hybrids.)		N/A	N/A	N/A	N/A
2007	Toyota	RAV4	N/A	N/A	N/A	N/A	YES PHASE 11 (Dealer Letter TBD; Owner Letter Start TBD) (Does not include Brake-to- Idle Upgrade)		N/A	N/A	N/A	N/A
2007	Toyota	Tacoma	N/A	N/A	N/A	N/A	YES PHASE 9 (Dealer Letter 7/16/2010; Owner Letter Start Late July 2010) (Does not include Brake-to-Idle		N/A	N/A	N/A	N/A

Year	Make		Lexus SSC 5LC (NHTSA Recall 05V565 - Accelerator Pedal Recall)	Toyota SSC 70F AWFM Pedal Iterference (NHTSA Recall 07E082)	Lexus SSC 7LB AWFM Pedal Iterference (NHTSA Recall 07E082)	Toyota SSC 90B (NHTSA Recall 09V023 - Floor Carpet Cover)	(NHTSA Recalls 09V388 and 10V023 -	Lexus SSC 9LG (NHTSA Recalls 09V388 and 10V023 - Floor Mat, Pedal Modification and Brake-to-Idle upgrade)	Sticking CTS Accelerator Pedal	Lexus SSC BLB Plastic Pad Embedded Into Floor Carpet (NHTSA Recall 11V115)	Lexus SSC BLC (Interim B2C) Driver's Side Floor Carpet Cover & Retention Clip (NHTSA Recall 11V112)	Toyota B0A (Interim B1A) Driver's Side Floor Carpet Cover and Retention Clips (NHTSA Recall 11V112)
2007	Toyota		N/A	N/A	N/A	N/A	YES PHASE 6 (Dealer Letter 4/16/2010; Owner Letter Start 5/5/2010) (Does not include Brake-to-Idle Upgrade)	N/A	YES 2/2/2010 (Customer can request new pedal. Dealers are not to offer new pedal)	N/A	N/A	N/A
2008	Lexus	ES350	N/A	N/A	Recall inititiated 9/28/2007 (Certain Vehicles)	N/A	N/A	YES - PHASE 1 (Dealer letter 12/21/2009; Owner Letter Start 12/31/2009)	N/A	N/A	N/A	N/A
2008	Lexus	IS 250	N/A	N/A	N/A	N/A	N/A	YES - PHASE 2 (Dealer letter 4/5/2010; Owner Letter Start 4/23/2010)	N/A	N/A	N/A	N/A
2008	Lexus	IS 350	N/A	N/A	N/A	N/A	N/A		N/A	N/A	N/A	N/A
2008	Lexus	IS F	N/A	N/A	N/A	N/A	N/A		N/A	N/A	N/A	N/A
2008	Lexus	IS C	N/A	N/A	N/A	N/A	N/A	,	N/A	N/A	N/A	N/A
2008	Lexus	LX570	N/A	N/A	N/A	N/A	N/A	YES PHASE 3 (Dealer Letter TBD; Owner Letter Start TBD) (Does not include Brake-to-Idle Upgrade)	N/A	N/A	N/A	N/A
2008	·	Pedals	N/A	Recall inititiated 9/28/2007 (Certain Vehicles)	N/A	N/A		N/A	YES 2/2/2010 (Customer can request new pedal. Dealers are not to offer new pedal)	N/A	N/A	N/A
2008	Toyota	Camry w/Denso Pedals	N/A	Recall inititiated 9/28/2007 (Certain Vehicles)	N/A	N/A	YES - PHASE 1 DENSO Pedals (Dealer letter 2/2/2010; Owner Letter Start 2/16/2010)	N/A	N/A	N/A	N/A	N/A
2008	Toyota	Camry HV	N/A	Recall inititiated 9/28/2007 (Certain Vehicles)	N/A	N/A	YES - PHASE 1 (Dealer letter 2/2/2010; Owner Letter Start 2/16/2010) Hybrid vehicles do not get Brake-to-Idle feature. Different system designed into Hybrids.)		YES 2/2/2010 (22 Specific Hybrid Vehicles built with CTS pedal and need to be fixed. Other Hybrids built with differenent Pedal)	N/A	N/A	N/A

Year	Make	Model	Lexus SSC 5LC (NHTSA Recall 05V565 - Accelerator Pedal Recall)	Toyota SSC 70F AWFM Pedal Iterference (NHTSA Recall 07E082)	•	Toyota SSC 90B (NHTSA Recall 09V023 - Floor Carpet Cover)	(NHTSA Recalls 09V388 and 10V023 - Floor Mat, Pedal	10V023 - Floor Mat, Pedal Modification and	Sticking CTS Accelerator Pedal (NHTSA Recall 10V017)	Lexus SSC BLB Plastic Pad Embedded Into Floor Carpet (NHTSA Recall 11V115)	Lexus SSC BLC (Interim B2C) Driver's Side Floor Carpet Cover & Retention Clip (NHTSA Recall 11V112)	Toyota B0A (Interim B1A) Driver's Side Floor Carpet Cover and Retention Clips (NHTSA Recall 11V112)
2008	Toyota	Highlander	N/A	N/A	N/A	N/A	YES PHASE 6 (Dealer Letter 4/16/2010; Owner Letter Start 4/30/2010) (Does not include Brake-to-Idle Upgrade)	N/A	N/A	N/A	N/A	N/A
2008	Toyota	Highlander HV	N/A	N/A	N/A	N/A	YES - PHASE 4 (Dealer letter 3/22/2010; Owner Letter Start 3/30/2010) Hybrid vehicles do not get Brake-to-Idle feature. Different system designed into Hybrids.)		N/A	N/A	N/A	N/A
2008	Toyota	Prius	N/A	N/A	N/A	N/A	YES - PHASE 5 (Dealer letter 4/12/2010; Owner Letter Start 4/23/2010) Hybrid vehicles do not get Brake-to-Idle feature. Different system designed into Hybrids.)	9-	N/A	N/A	N/A	N/A
2008	Toyota	RAV4	N/A	N/A	N/A	S C	YES PHASE 11 (Dealer Letter TBD; Owner Letter Start TBD) (Does not include Brake-to- Idle Upgrade)	N/A	N/A	N/A	N/A	N/A
2008	Toyota	Sequoia	N/A	N/A	N/A	N/A	N/A	N/A	YES 2/2/2010 (Customer can request new pedal. Dealers are not to offer new pedal)	N/A	N/A	N/A
2008	Toyota	Tacoma	N/A	N/A	N/A	N/A	Letter 7/16/2010; Owner Letter Start Late July 2010) (Does not include Brake-to-Idle		N/A	N/A	N/A	N/A
	Toyota	Tundra	N/A	N/A	N/A	N/A	YES PHASE 6 (Dealer Letter 4/16/2010; Owner Letter Start 5/5/2010) (Does not include Brake-to-Idle Upgrade)		YES 2/2/2010 (Customer can request new pedal. Dealers are not to offer new pedal)	N/A	N/A	N/A
2009	Lexus	ES350	N/A	N/A	N/A	N/A	N/A	YES - PHASE 1 (Dealer letter 12/21/2009; Owner Letter Start 12/31/2009)	N/A	N/A	N/A	N/A

## Toyota Recall Matrix

Year	Make	Model	Lexus SSC 5LC (NHTSA Recall 05V565 - Accelerator Pedal Recall)	Toyota SSC 70F AWFM Pedal Iterference (NHTSA Recall 07E082)	Lexus SSC 7LB AWFM Pedal Iterference (NHTSA Recall 07E082)	Toyota SSC 90B (NHTSA Recall 09V023 - Floor Carpet Cover)	(NHTSA Recalls 09V388 and 10V023 - Floor Mat, Pedal	Lexus SSC 9LG (NHTSA Recalls 09V388 and 10V023 - Floor Mat, Pedal Modification and Brake-to-Idle upgrade)	Toyota SSC A0A - Sticking CTS Accelerator Pedal (NHTSA Recall 10V017)	Lexus SSC BLB Plastic Pad Embedded Into Floor Carpet (NHTSA Recall 11V115)	Lexus SSC BLC (Interim B2C) Driver's Side Floor Carpet Cover & Retention Clip (NHTSA Recall 11V112)	Toyota B0A (Interim B1A) Driver's Side Floor Carpet Cover and Retention Clips (NHTSA Recall 11V112)
2009	Lexus	IS 250	N/A	N/A	N/A	N/A	N/A	YES - PHASE 2 (Dealer letter 4/5/2010; Owner Letter Start 4/23/2010)	N/A	N/A	N/A	N/A
2009	Lexus	IS 350	N/A	N/A	N/A	N/A	N/A	YES - PHASE 2 (Dealer letter 4/5/2010; Owner Letter Start 4/23/2010)	N/A	N/A	N/A	N/A
2009	Lexus	IS F	N/A	N/A	N/A	N/A	N/A	YES - PHASE 2 (Dealer letter 4/5/2010; Owner Letter Start 4/23/2010)	N/A	N/A	N/A	N/A
2009	Lexus	IS C	N/A	N/A	N/A	N/A	N/A	YES - PHASE 2 (Dealer letter 4/5/2010; Owner Letter Start 4/23/2010)	N/A	N/A	N/A	N/A
2009	Lexus	LX570	N/A	N/A	N/A	N/A	N/A	YES PHASE 3 (Dealer Letter TBD; Owner Letter Start TBD) (Does not include Brake-to-Idle Upgrade)	N/A	N/A	N/A	N/A
2009	Toyota	4Runner	N/A	N/A	N/A	N/A	YES PHASE 10 (Dealer Letter 2/24/2011; Owner Letter Start Late April 2011) (Does not include Brake-to-Idle	N/A	N/A	N/A	N/A	N/A
2009	Toyota	Avalon	N/A	N/A	N/A	N/A	YES - PHASE 3 (Dealer Letter 2/23/2010; Owner Letter Start 3/1/2010)	N/A	YES 2/2/2010 (Customer can request new pedal. Dealers are not to offer new pedal)	N/A	N/A	N/A
2009	Toyota	Camry w/CTS Pedals	N/A	N/A	N/A	N/A	YES - PHASE 2 CTS Pedals (Dealer Letter 2/4/2010; Owner Letter Start 2/16/2010)	N/A	I	N/A	N/A	N/A
2009	Toyota	Camry w/Denso Pedals	N/A	N/A	N/A	N/A	YES - PHASE 1 DENSO Pedals (Dealer letter 2/2/2010; Owner Letter Start 2/16/2010)	N/A	N/A	N/A	N/A	N/A
2009	Toyota	Camry HV	N/A	N/A	N/A	N/A	YES - PHASE 1 (Dealer letter 2/2/2010; Owner Letter Start 2/16/2010) Hybrid vehicles do not get Brake-to-Idle feature. Different system designed into Hybrids.)	N/A	YES 2/2/2010 (22 Specific Hybrid Vehicles built with CTS pedal and need to be fixed. Other Hybrids built with differenent Pedal)	N/A	N/A	N/A

Year	Make	Model	Lexus SSC 5LC (NHTSA Recall 05V565 - Accelerator Pedal Recall)	Toyota SSC 70F AWFM Pedal Iterference (NHTSA Recall 07E082)	Lexus SSC 7LB AWFM Pedal Iterference (NHTSA Recall 07E082)	Toyota SSC 90B (NHTSA Recall 09V023 - Floor Carpet Cover)	(NHTSA Recalls 09V388 and 10V023 -	10V023 - Floor Mat, Pedal Modification and	Toyota SSC A0A - Sticking CTS Accelerator Pedal (NHTSA Recall 10V017)	Lexus SSC BLB Plastic Pad Embedded Into Floor Carpet (NHTSA Recall 11V115)	Lexus SSC BLC (Interim B2C) Driver's Side Floor Carpet Cover & Retention Clip (NHTSA Recall 11V112)	Toyota B0A (Interim B1A) Driver's Side Floor Carpet Cover and Retention Clips (NHTSA Recall 11V112)
2009	Toyota	Corolla	N/A	N/A	N/A	N/A	YES PHASE 7 (Dealer Letter 6/8/2010; Owner Letter Start 6/21/2010) (Does not include Brake-to-Idle Upgrade)	N/A	YES 2/2/2010 (Customer can request new pedal. Dealers are not to offer new pedal)	N/A	N/A	N/A
2009	Toyota	Highlander	N/A	N/A	N/A	N/A		N/A	YES 2/2/2010 (Customer can request new pedal. Dealers are not to offer new pedal)	N/A	N/A	N/A
2009	Toyota	Highlander HV	N/A	N/A	N/A	N/A	YES - PHASE 4 (Dealer letter 3/22/2010; Owner Letter Start 3/30/2010) Hybrid vehicles do not get Brake-to-Idle feature. Different system designed into Hybrids.)	N/A	N/A	N/A	N/A	N/A
2009	Toyota	Matrix	N/A	N/A	N/A	N/A		N/A	YES (Customer can request new pedal. Dealers are not to offer new pedal)	N/A	N/A	N/A
2009	Toyota	Prius	N/A	N/A	N/A	N/A	YES - PHASE 5 (Dealer letter 4/12/2010; Owner Letter Start 4/23/2010) Hybrid vehicles do not get Brake-to-Idle feature. Different system designed into Hybrids.)	N/A	N/A	N/A	N/A	N/A
2009	Toyota	RAV4	N/A	N/A	N/A	N/A	YES PHASE 11 (Dealer Letter TBD; Owner Letter Start TBD) (Does not include Brake-to- Idle Upgrade)	N/A	YES (Customer can request new pedal. Dealers are not to offer new pedal)	N/A	N/A	N/A
2009	Toyota	Sequoia	N/A	N/A	N/A	N/A		N/A	YES (Customer can request new pedal. Dealers are not to offer new pedal)	N/A	N/A	N/A
2009	Toyota	Tacoma	N/A	N/A	N/A	N/A	YES PHASE 9 (Dealer Letter 7/16/2010; Owner Letter Start Late July 2010) (Does not include Brake-to-Idle	N/A	N/A	N/A	N/A	N/A

Year	Make	Model	Lexus SSC 5LC (NHTSA Recall 05V565 - Accelerator Pedal Recall)	Toyota SSC 70F AWFM Pedal Iterference (NHTSA Recall 07E082)	Lexus SSC 7LB AWFM Pedal Iterference (NHTSA Recall 07E082)	Toyota SSC 90B (NHTSA Recall 09V023 - Floor Carpet Cover)	(NHTSA Recalls 09V388 and 10V023 - Floor Mat, Pedal	10V023 - Floor Mat, Pedal Modification and	Sticking CTS Accelerator Pedal (NHTSA Recall 10V017)	Lexus SSC BLB Plastic Pad Embedded Into Floor Carpet (NHTSA Recall 11V115)	Lexus SSC BLC (Interim B2C) Driver's Side Floor Carpet Cover & Retention Clip (NHTSA Recall 11V112)	Toyota B0A (Interim B1A) Driver's Side Floor Carpet Cover and Retention Clips (NHTSA Recall 11V112)
2009	Toyota	Tundra	N/A	N/A	N/A	N/A	YES PHASE 6 (Dealer Letter 4/16/2010; Owner Letter Start 5/5/2010) (Does not include Brake-to-Idle Upgrade)	N/A	YES 2/2/2010 (Customer can request new pedal. Dealers are not to offer new pedal)	N/A	N/A	N/A
2009	Toyota	Venza	N/A	N/A	N/A	N/A	YES PHASE 9 (Dealer Letter 7/16/2010; Owner Letter Start Late July 2010) (Does not include Brake-to-Idle	N/A	N/A	N/A	N/A	N/A
2010	Lexus	ES350	N/A	N/A	N/A	N/A	N/A	YES - PHASE 1 (Dealer letter 12/21/2009; Owner Letter Start 12/31/2009)	N/A	N/A	N/A	N/A
2010	Lexus	IS 250	N/A	N/A	N/A	N/A	N/A	YES - PHASE 2 (Dealer letter 4/5/2010; Owner Letter Start 4/23/2010)	N/A	N/A	N/A	N/A
2010	Lexus	IS 350	N/A	N/A	N/A	N/A	N/A	YES - PHASE 2 (Dealer letter 4/5/2010; Owner Letter Start 4/23/2010)	N/A	N/A	N/A	N/A
2010	Lexus	IS F	N/A	N/A	N/A	N/A	N/A		N/A	N/A	N/A	N/A
2010	Lexus	IS C	N/A	N/A	N/A	N/A	N/A		N/A	N/A	N/A	N/A
2010	Lexus	LX570	N/A	N/A	N/A	N/A	N/A		N/A	N/A	N/A	N/A
2010	Toyota	Avalon	N/A	N/A	N/A	N/A	YES - PHASE 3 (Dealsr Letter 2/23/2010; Owner Letter Start 3/1/2010)		YES 2/2/2010 (Customer can request new pedal. Dealers are not to offer new pedal)	N/A	N/A	N/A
2010	Toyota	Camry w/CTS Pedals	N/A	N/A	N/A	N/A	YES - PHASE 2 CTS Pedals (Dealer Letter 2/4/2010; Owner Letter Start 2/16/2010)	N/A	YES 2/2/2010 (Customer can request new pedal. Dealers are not to offer new pedal)	N/A	N/A	N/A

Year	Make	Model	Lexus SSC 5LC (NHTSA Recall 05V565 - Accelerator Pedal Recall)	Toyota SSC 70F AWFM Pedal Iterference (NHTSA Recall 07E082)	Lexus SSC 7LB AWFM Pedal Iterference (NHTSA Recall 07E082)	Toyota SSC 90B (NHTSA Recall 09V023 - Floor Carpet Cover)	Toyota SSC 90L & 91L (NHTSA Recalls 09V388 and 10V023 - Floor Mat, Pedal Modification and Brake- to-Idle upgrade)	Lexus SSC 9LG (NHTSA Recalls 09V388 and 10V023 - Floor Mat, Pedal Modification and Brake-to-Idle upgrade)	Sticking CTS Accelerator Pedal (NHTSA Recall 10V017)	Lexus SSC BLB Plastic Pad Embedded Into Floor Carpet (NHTSA Recall 11V115)	Lexus SSC BLC (Interim B2C) Driver's Side Floor Carpet Cover & Retention Clip (NHTSA Recall 11V112)	Toyota B0A (Interim B1A) Driver's Side Floor Carpet Cover and Retention Clips (NHTSA Recall 11V112)
2010		Camry w/Denso Pedals	N/A	N/A	N/A	N/A	YES - PHASE 1 DENSO Pedals (Dealer letter 2/2/2010; Owner Letter Start 2/16/2010)	N/A	N/A	N/A	N/A	N/A
2010		Camry w/Sport Pedals	N/A	N/A	N/A	N/A	YES - PHASE 8 Sport Pedals (Dealer Letter 7/2/2010; Owner Letter Start 7/16/2010)	N/A	N/A	N/A	N/A	N/A
2010	Toyota	Camry HV	N/A	N/A	N/A	N/A	YES - PHASE 1 (Dealer letter 2/2/2010; Owner Letter Start 2/16/2010) Hybrid vehicles do not get Brake-to-Idle feature. Different system designed into Hybrids.)	5	YES (22 Specific Hybrid Vehicles built with CTS pedal and need to be fixed. Other Hybrids built with differenent Pedal)	N/A	N/A	N/A
2010	Toyota	Corolla	N/A	N/A	N/A	N/A	YES PHASE 7 (Dealer Letter 6/8/2010; Owner Letter Start 6/21/2010) (Does not include Brake-to-Idle Upgrade)	N/A	YES 2/2/2010 (Customer can request new pedal. Dealers are not to offer new pedal)	N/A	N/A	N/A
2010	Toyota	Highlander	N/A	N/A	N/A	N/A		N/A		N/A	N/A	N/A
2010	Toyota	Highlander HV	N/A	N/A	N/A	N/A	YES - PHASE 4 (Dealer letter 3/22/2010; Owner Letter Start 3/30/2010) Hybrid vehicles do not get Brake-to-Idle feature. Different system designed into Hybrids.)			N/A	N/A	N/A
2010	Toyota	Matrix	N/A	N/A	N/A	N/A	YES PHASE 7 (Dealer Letter 6/8/2010; Owner Letter Start 6/21/2010) (Does not include Brake-to-Idle Upgrade)		YES 2/2/2010 (Customer can request new pedal. Dealers are not to offer new pedal)	N/A	N/A	N/A
2010	Toyota	RAV4	N/A	N/A	N/A	N/A	YES PHASE 11 (Dealer Letter TBD; Owner Letter Start TBD) (Does not include Brake-to- Idle Upgrade)	N/A		N/A	N/A	N/A

Year			(NHTSA Recall 05V565 - Accelerator Pedal Recall)	Recall 07E082)	Recall 07E082)	Toyota SSC 90B (NHTSA Recall 09V023 - Floor Carpet Cover)	(NHTSA Recalls 09V388 and 10V023 - Floor Mat, Pedal Modification and Brake to-Idle upgrade)	Lexus SSC 9LG (NHTSA Recalls 09V388 and 10V023 - Floor Mat, Pedal Modification and Brake-to-Idle upgrade)	Sticking CTS Accelerator Pedal (NHTSA Recall 10V017)	Lexus SSC BLB Plastic Pad Embedded Into Floor Carpet (NHTSA Recall 11V115)	Lexus SSC BLC (Interim B2C) Driver's Side Floor Carpet Cover & Retention Clip (NHTSA Recall 11V112)	Toyota B0A (Interim B1A) Driver's Side Floor Carpet Cover and Retention Clips (NHTSA Recall 11V112)
2010	Toyota	Sequoia	N/A	N/A	N/A	N/A	N/A	5	YES 2/2/2010 (Customer can request new pedal. Dealers are not to offer new pedal)		N/A	N/A
2010	Toyota	Tacoma	N/A	N/A	N/A	N/A	YES PHASE 9 (Dealer Letter 7/16/2010; Owner Letter Start Late July 2010) (Does not include Brake-to-Idle	N/A	N/A	N/A	N/A	N/A
2010	Toyota	Tundra	N/A	N/A	N/A	N/A	YES PHASE 6 (Dealer Letter 4/16/2010; Owner Letter Start 5/5/2010) (Does not include Brake-to-Idle Upgrade)	N/A	YES 2/2/2010 (Customer can request new pedal. Dealers are not to offer new pedal)	N/A	N/A	N/A
2010	Toyota	Venza	N/A	N/A	N/A	N/A	YES PHASE 9 (Dealer Letter 7/16/2010; Owner Letter Start Late July 2010) (Does not include Brake-to-Idle	N/A	N/A	N/A	N/A	N/A
2011	Lexus	LX570	N/A	N/A	N/A	N/A	N/A	YES PHASE 3 (Dealer Letter TBD; Owner Letter Start TBD) (Does not include Brake-to-Idle Upgrade)	N/A	N/A	N/A	N/A
2011		Camry w/Sport Pedals	N/A	N/A	N/A	N/A	YES - PHASE 8 Sport Pedals (Dealer Letter 7/2/2010; Owner Letter Start 7/16/2010)	N/A	N/A	N/A	N/A	N/A